

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

Xiao Chen

ESTIMATE OF REPAIR

Veh# : GBK1677J

Model:

TOYOTA DYNA

Accident Date : 21/6/2024

16/1/2020

Location : PIE TOWARDS TUAS BEFORE STEVEN ROAD EXIT

3P:

YM6832L (INCOME)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front panel <i>New Regis</i>	1,378.70	+	
2	1 pc	Front panel emblem - DYNA <i>New</i>	91.75	-	
3	1 pc	Front panel sealant <i>New</i>		80.00	+
4	1 pc	Front panel inner lower panel <i>Wiper</i> <i>Replaced</i>	814.5		
5	1 pc	Front grille <i>Replaced</i>	852.20 685		
6	1 pc	Front grille Logo <i>New</i>	74.00	2	
7	1 pc	Front grille gasket seal <i>New</i>	35.50	+	
8	1 set	Front grille clip <i>New</i>		50.00	30
9	2 pcs	Front headlamp R/L <i>2H Replaced</i>	2,825.00	1412.50	1100
10	1 pc	Front bumper <i>Replaced</i>	783.50		
11	2 pcs	Front bumper bracket R/L <i>New</i>	772.40	+	
12	2 pcs	Front bumper foglamp cover R/L <i>New</i>	138.00	+	
13	1 pc	Front no. plate <i>But</i>		35.00	30
14	1 pc	Front no. plate holder <i>New</i>		50.00	+
15	1 pc	Rear tailgate <i>Replaced</i>	1,520.00		
16	1 pc	Rear tailgate 70KM/H sticker		25.00	15
17	1 pc	Rear tailgate 13 PAX sticker		25.00	15
18	1 pc	Rear tailgate DYNA sticker	59.20	✓	
19	1 pc	Rear tail gate TOYOTA sticker	130.00	✓	
20	4 pcs	Rear tailgate hinges <i>New</i>	277.20	+	
21	1 pc	Rear tailgate lower panel <i>Replaced</i>	698.10	+	
22	2pcs	Rear tailgate flip lock handle LH & RH <i>New</i>	318.80	+	
23	2pcs	Rear taillamp LH & Rh <i>New</i>	628.60	+	
24	2pcs	Rear taillamp bracket LH & RH <i>New</i>	143.80	+	
25	2pcs	Rear rubber stopped LH & RH	93.00	+	
26	2pcs	Rear rubber stopped bracket LH & RH	197.20	+	

27	1 pc	Rear no. plate	3pc	35.00	+
28	1 pc	Rear no. plate holder	5023.45 SN: 290	50.00	+
29	1 set	Rear reverse sensor	3767.58	250.00	20
30	1 set	Rear reverse sensor bracket	new	80.00	+
	1pc	Rear Step	\$300 But		
			\$200 ✓		
			(SN)		
		Sub Total:	11,831.45	680.00	0.00
			25%	0%	0%
		After Less %:	8,873.59	680.00	0.00
		Labour			
1		To remove & refix accident damaged parts & realign accident affected area.		1,400.00	700
2		To spray paint on accident affected area.	1510	1,200.00	700
3		To check wiring, layout & rewire parking sensor.		100.00	50
4		To rust proof affected area.		100.00	60
		Sub Total:		2,800.00	
		Total:		12,353.59	
		After Less 20%:		9,882.87	

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Adrian
2/s 25/06/24
06 days



AL 8778 1999
24 hr accident call



total: 5762.58
2/s: 4.6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Wrong Calculation

4.6K

4.6K