

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 15.10.2024

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLT3714G**
MODEL : **HONDA VEZEL**
DATE OF ACCIDENT : 09.10.2024
TIME OF ACCIDENT : 15:05 HOURS

Hui Kong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	GRILLE LOGO GARNISH <i>lt</i>	1	\$ 485.00	\$ 485.00
2	HEADLAMP <i>lt KAA</i>	2	\$ 1,958.40	\$ 3,916.80
3	FRONT FENDER ARCD GARNISH LH <i>lt</i>	1	\$ 195.00	\$ 195.00
4	FRONT WIPER PANEL GARNISH <i>lt</i>	1	\$ 492.30	\$ 492.30
5	FRONT WIPER BLADE <i>lt</i>	2	\$ 98.50	\$ 197.00
6	FRONT WINDSCREED GLASS <i>lt</i>	1	\$ 1,582.00	\$ 1,582.00
7	FRONT WINDSCREED GLASS MOULDING <i>lt</i>	1	\$ 295.00	\$ 295.00
8	SIDE MIRROR LH <i>lt</i>	1	\$ 841.60	\$ 841.60
9	FRONT DOOR OUTER MOULDING LH <i>lt</i>	1	\$ 87.00	\$ 87.00
10	FRONT DOOR BLACK STICKER LH <i>lt</i>	1	\$ 95.00	\$ 95.00
11	FRONT DOOR WINDOR GLASS LH <i>lt</i>	1	\$ 486.30	\$ 486.30
12	REAR DOOR WINDOR GLASS LH <i>lt</i>	1	\$ 538.60	\$ 538.60
13	REAR DOOR OUTER MOULDING LH <i>lt</i>	1	\$ 95.00	\$ 95.00

TOTAL PRICE \$ 9,306.60
LESS 20% \$ 1,861.32
SUB TOTAL PRICE \$ 7,445.28

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT WIPER PANEL GARNISH CLIP (SET) <i>lt</i>	1	\$ 30.00	\$ 30.00

TOTAL \$ 30.00

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLT3714G**
MODEL : **HONDA VEZEL**
DATE OF ACCIDENT : 09.10.2024
TIME OF ACCIDENT : 15:05 HOURS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	100
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1000
3	REMOVE AND REFIX FRONT AND REAR DOOR WINDOR GLASS LH	\$ 180.00	80
4	REMOVE AND REFIX FRONT WINDSCREEN GLASS	\$ 150.00	120

TOTAL \$ 3,130.00

TOTAL PARTS COST : \$ 7,475.28
TOTAL LABOUR COST : \$ 3,130.00
TOTAL REPAIR COST : \$ 10,605.28

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adnan L
2/s 17/10/24

04 Days

total: 6647.92

1/s: 5310 ✓