



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO XE 3449J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT CORNER PANEL LH	BROKEN	\$1,950.00	\$1,950.00
1	FRONT CORNER PANEL BRACKET LH	BROKEN	\$480.00	\$480.00
1	FRONT CORNER PANEL INNER COVER LH	MISSING	\$240.00	\$240.00
1	FRONT HEADLAMP COVER LH	NOT NECESSARY	\$380.00	\$0.00
1	FRONT HEADLAMP LH	NOT NECESSARY	\$700.00	\$0.00
1	FRONT SIGNAL LAMP LH (BROKEN)	OLD DAMAGED	\$350.00	\$0.00
1	FRONT CORNER BUMPER LH	NOT NECESSARY	\$1,350.00	\$0.00
1	FRONT LOWER STEP PLATE LH	NOT NECESSARY	\$450.00	\$0.00
1	FRONT DOOR PANEL LH	TO REPAIR SEE LABOUR	\$3,600.00	\$0.00
1	FRONT DOOR TAPE LH	NOT NECESSARY	\$120.00	\$0.00
1	FRONT DOOR MOULDING LH	NOT NECESSARY	\$160.00	\$0.00
1	FRONT DOOR HINGE LH	NOT NECESSARY	\$180.00	\$0.00
1	SIDE MIRROR LH	NOT NECESSARY	\$680.00	\$0.00
	LESS 10.00% DISCOUNT		(\$1,064.00)	(\$267.00)
			\$9,576.00	\$2,403.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR COMPANY DECAL (SN)	NOT NECESSARY	\$150.00	\$0.00
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	\$60.00	\$0.00
			\$210.00	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	CHECK WIRING AND LIGHTNING SYSTEM		\$80.00	\$30.00
	REMOVE AND REFIT FRONT DOOR TRIMS AND GARNISHES	NOT NECESSARY	\$150.00	\$0.00
	PANEL BEATING ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT DOOR PANEL LH		\$1,200.00	\$300.00
	SPRAY PAINTING ON AFFECTED AREAS		\$1,200.00	\$400.00
	APPLY ANTI RUST ON AFFECTED AREAS	NOT NECESSARY	\$150.00	\$0.00
			\$2,780.00	\$730.00

GRAND TOTAL			\$12,566.00	\$3,133.00
--------------------	--	--	--------------------	-------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)		\$3,133.00
Report Ref No: CS/LIP24100393/Evh3m4			

MARKET VALUE: \$45,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$12,190.00=NETT VALUE: \$32,810.00

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.