



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24100393/Evh3m4
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	04/11/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 7698E	Veh. Inspected	XE 3449J
Policy No.	-	Coverage	0
Claim No.	AVS24/3244	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	23/10/2024

2. Vehicle Details

Make & Model	SCANIA P310DB4X2HSZ	C.C	9291
Engine No.	DC09110L017021749	Year of Reg.	19/09/2017
Chassis No.	YS2P4X20009226162	Colour	WHITE
Odometer	432456 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	295/80R22.5	BRIDGESTONE	5
L/H Front Tyre	295/80R22.5	BRIDGESTONE	5
R/H Rear Tyre	295/80R22.5	BRIDGESTONE	5
L/H Rear Tyre	295/80R22.5	BRIDGESTONE	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/10/2024	Inspection Date	24/10/2024
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days