

Vehicle number	XE3449J
Make / Model	SCANIA P310DB4X2HSZ
Chassis number	YS2P4X20009226162
Accident date	15-10-24
Reference	2410-21

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT CORNER PANEL LH / BR	1950.00
1	FRONT CORNER PANEL BRACKET LH / BR	480.00
1	FRONT CORNER PANEL INNER COVER LH / MIS	240.00
1	FRONT HEADLAMP COVER LH X nn	380.00
1	FRONT HEADLAMP LH X nn	700.00
1	FRONT SIGNAL LAMP LH X old damage / Br	350.00
1	FRONT CORNER BUMPER LH X nn	1350.00
1	FRONT LOWER STEP PLATE LH X nn	450.00
1	FRONT DOOR PANEL LH X R	3600.00
1	FRONT DOOR TAPE LH X nn	120.00
1	FRONT DOOR MOULDING LH X nn	160.00
1	FRONT DOOR HINGE LH X nn	180.00
1	SIDE MIRROR LH X nn	680.00
		10640.00
	Less 10%	1064.00
		9576.00
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	FRONT DOOR COMPANY DECAL X nn	150.00
1 SET	FRONT BUMPER CLIP X nn	60.00
	Subtotal	210.00
	Balance C/F	9786.00
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	80.00 30
2	REMOVE AND REFIT FRONT DOOR TRIMS AND GARNISHES	150.00 X
3	PANEL BEATING ON AFFECTED AREAS	1200.00 300
4	SPRAY PAINTING ON AFFECTED AREAS	1200.00 400
5	APPLY ANTI RUST ON AFFECTED AREAS	150.00 X
	Subtotal	2780.00
	Grand total	12566.00

Steve (LKK)
24/10/24, 11.00am
w L
L/S
my LKK
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company