

ESTIMATE

Our Ref: C20240089/TP
Vehicle: SLW4545E Toyota Yaris
Chassis no.: JTDKBAB330L011380

Date of Loss: 21/10/2024
Insurer: MSIG
Date of Survey: 25/10/2024

Items	Qty	List Items
1	1	Front bonnet
2	1	Front fender LH
3	1	Front fender protector
4	1	Front headlamp LH
5	1	Front bumper
6	1	Front bumper side retainer LH

	Amount \$	
R	1,208.30	X
10/30	1,081.00	—
Scrap/alc	291.20	X
holder	1,968.90	—
11	643.20	X
11	133.80	X
Sub-total	5,326.40	
Less 25%	-1,331.60	
Total Parts	3,994.80	

Labour charges

7	To check front electrical wiring	120.00	20
8	To respray painting and etc	1,000.00	400
9	Panel beating, cut, weld remove & replacing above parts	1,000.00	300
Total Labour		2,120.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

6,114.80

Not Authorised
in
works

25/10/24

1P \$3007.43

3 days

Emphe. before party.

P. 3049.9
252
2287.43
720
3007.43

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: