



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	/ 0
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
Z TEXT							
TP CLAIM COMFORT /							
DOA							
SUR							
00 REPAIR DAYS							
E PNT88000							6400.00
TO REPLACE REAR BUMPER, TAIL GATE, REAR END PANEL,							
REAR FLOOR PANEL, REAR LHS FENDER							
REPAIR ACCIDENT AFFECTED AREA							
E PNT98000							3300.00
PAINT WORK REAR BUMPER, TAIL GATE, REAR END PANEL, REAR LHS FENDER,							
REAR FLOOR PANEL							
E PNT88000							600.00
TO MOUNT VEHICLE ON FLOOR BENCH TO ALIGN CHASSIS							
E PNT88000							240.00
TO REMOVE & REFIT REAR PARKING SENSOR							
E PNT88000							640.00
TO TANSFER PARTS & COMPONENTS TO NEW TAIL GATE							
E PNT88000							380.00
TO REMOVE & REFIT REAR WINDSCREEN							
E PNT88000							150.00
TO PERFORM WATER LEAK TEST							
M SUNDRY							120.00
SUPPLY AND APPLY WINDSCREEN SEALANT							
E PNT88000							640.00
TO REMOVE & REFIT ELECTRONIC, PARTS, AND COMPONENT ON REAR BOOT							
COMPARTMENT TO FACILITATE THE REPAIR							
M SUNDRY							320.00
ANTI-RUST PROOFING							
M SUNDRY							320.00
APPLY BODY SEALANT ON AFFECTED AREA							
E PNT88000							640.00
TO REMOVE & REFIT REAR SEAT BENCH							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	/ 0
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A 54900099								960.00
TO REMOVE & REFIT FUEL TANK								
A 54900099								280.00
TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								380.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								85.00
SUPPLY REAR LICENSE PLATE WITH CASING								
M SUNDRY								50.00
C&C EMBLEM								
M SUNDRY								80.00
SUNDRIES								
M COVER-RR BUMPER,UPR					1.00	940.00	00.00	940.00
M COVER-RR BUMPER LWR					1.00	511.00	00.00	511.00
M SKID PLATE-RR BUMPER					1.00	452.00	00.00	452.00
M COVER-RR BUMPER UNDER,LH					1.00	33.00	00.00	33.00
M LAMP ASSY-SIDE T/SIG & REAR,LH					1.00	151.00	00.00	151.00
M LAMP ASSY-SIDE T/SIG & REAR,RH					1.00	151.00	00.00	151.00
M ANTENNA ASSY-SMARTKEY					1.00	45.00	00.00	45.00
M WIRING HARNESS-RR BUMPER					1.00	427.00	00.00	427.00
M BEAM-RR BUMPER					1.00	313.00	00.00	313.00
M BRACKET-RR BEAM LWR MTG,LH					1.00	37.00	00.00	37.00
M BRACKET-RR BEAM LWR MTG,RH					1.00	37.00	00.00	37.00
M BRACKET-RR BUMPER RAIL LWR,LH					1.00	37.00	00.00	37.00
M BRACKET-RR BUMPER RAIL LWR,RH					1.00	6.00	00.00	6.00
M STAY-RR BUMPER LH					1.00	67.00	00.00	67.00
M STAY-RR BUMPER RH					1.00	67.00	00.00	67.00
M BRACKET ASSY-RR BUMPER SIDE,LH					1.00	23.00	00.00	23.00
M BRACKET ASSY-RR BUMPER SIDE,RH					1.00	23.00	00.00	23.00
M LAMP ASSY-REAR FOG					1.00	133.00	00.00	133.00
M PANEL ASSY-TAIL GATE					1.00	2136.00	00.00	2136.00
M HINGE ASSY-TAIL GATE,LH					2.00	25.00	00.00	50.00
M DRIVE UNIT ASSY-PWR T/GATE,LH					1.00	853.00	00.00	853.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	/ 0
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M DRIVE UNIT ASSY-PWR T/GATE,RH		1.00	853.00	00.00	853.00
M TRIM ASSY-TAIL GATE LWR		1.00	383.00	00.00	383.00
M W/STRIP-TAIL GATE OPNG		1.00	130.00	00.00	130.00
M W/STRIP ASSY-T/GATE A/PINCH,LH		1.00	223.00	00.00	223.00
M W/STRIP ASSY-T/GATE A/PINCH,RH		1.00	223.00	00.00	223.00
M OUTSIDE HDL & LOCK ASSY-T/LID		1.00	177.00	00.00	177.00
M GARNISH ASSY-TAIL GATE		1.00	624.00	00.00	624.00
M SCREW-TAPPING		2.00	1.00	00.00	2.00
M SEALING PAD-B/PNL MLDG NO.2		18.00	1.00	00.00	18.00
M CLIP-SIDE GARNISH MTG		10.00	3.00	00.00	30.00
M T/SCREW-COUNTERSINK HEAD		8.00	1.00	00.00	8.00
M SEALING PAD-B/PNL MLDG NO.4		2.00	1.00	00.00	2.00
M SEALING PAD-B/PNL MLDG NO.1		2.00	4.00	00.00	8.00
M PAD-TAIL GATE GARNISH		2.00	2.00	00.00	4.00
M CAP NUT-RADIATOR,UPR		2.00	4.00	00.00	8.00
M SEALING PAD-B/PNL MLDG NO.3		2.00	1.00	00.00	2.00
M EMBLEM-KIA		1.00	54.00	00.00	54.00
M EMBLEM-CARNIVAL		1.00	89.00	00.00	89.00
M PANEL ASSY-BACK		1.00	633.00	00.00	633.00
M TRIM ASSY-RR TRANSVERSE		1.00	99.00	00.00	99.00
M PAD-WINDSHIELD GLASS		14.00	2.00	00.00	28.00
M TERMINAL-RR WDO GLASS DEFOGGER		2.00	18.00	00.00	36.00
P STOPPER-TAIL GATE GLASS		2.00	3.00	00.00	6.00
M HOUSING-FUEL FILLER DR		1.00	268.00	00.00	268.00
M LAMP ASSY-CENTER GARNISH		1.00	1910.00	00.00	1910.00
M GUARD ASSY-REAR WHEEL,LH		1.00	193.00	00.00	193.00
M ULTRASONIC SENSOR-S.P.A.S		4.00	177.00	00.00	708.00
M TRIM ASSY-TAIL GATE UPR		1.00	44.00	00.00	44.00
M TRIM ASSY-TAIL GATE FRAME SIDE		1.00	29.00	00.00	29.00
M TRIM ASSY-TAIL GATE FRAME SIDE		1.00	29.00	00.00	29.00
M PAD-ANTINOISE		10.00	1.00	00.00	10.00
M TRIM ASSY-LUGGAGE SIDE LH		1.00	626.00	00.00	626.00
M TRIM ASSY-LUGGAGE SIDE RH		1.00	670.00	00.00	670.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
JONATHAN PETER LAU	Cust No/Name /JONATHAN PETER LAU
24 ETTRICK TERRACE	Reg No/Reg Date SND3545M / 23/12/2021
01-01 FRANKEL ESTATE	Date In/Mileage / 0
SINGAPORE 458587	Chassis No KNANC81BMN6151996
Contact No Mobile: 96688763	Engine No D4HEMH705449
	Make/Model KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL ASSY-REAR FLOOR,RR	1.00	264.00	00.00	264.00
M PANEL ASSY-REAR FLOOR,FRT	1.00	498.00	00.00	498.00
M WIRING ASSY-FLOOR	1.00	3974.00	00.00	3974.00
M CARPET ASSY-REAR FLOOR	1.00	449.00	00.00	449.00

Estimate

Confirm & accepted by

Nett	35,389.00
9% GST on	3185.01
Total Payable	38,574.01

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.