



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|-------------------------------------|
| JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763 | Cust No/Name | /JONATHAN PETER LAU |
| | Reg No/Reg Date | SND3545M / 23/12/2021 |
| | Date In/Mileage | / 0 |
| | Chassis No | KNANC81BMN6151996 |
| | Engine No | D4HEMH705449 |
| | Make/Model | KIA/CARNIVAL 2.2 A D SR G641 8 SEAT |
| | Colour/Trim | ABP AURORA BLACK / GYT BLACK/GRAY |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|--|-------|-------------------|------------|---------------------|-------------------------|
| CSM00087 | Cash | 22/10/2024/ 15:55 | TLL | 1210/ Lim Teng Keat | 11536 |
| Description of Goods / Services | | Qty | Unit Price | Disc% | Amount |
| Z TEXT TP CLAIM COMFORT / DOA SUR OO REPAIR DAYS | | | | | 4480 6400.00 |
| E PNT88000 TO REPLACE REAR BUMPER, TAIL GATE, REAR END PANEL, REAR FLOOR PANEL, REAR LHS FENDER REPAIR ACCIDENT AFFECTED AREA | | | | | 2750 3300.00 |
| E PNT98000 PAINT WORK REAR BUMPER, TAIL GATE, REAR END PANEL, REAR LHS FENDER REAR FLOOR PANEL | | | | | 600.00 |
| E PNT88000 TO MOUNT VEHICLE ON FLOOR BENCH TO ALIGN CHASSIS | | | | | 120 240.00 |
| E PNT88000 TO REMOVE & REFIT REAR PARKING SENSOR | | | | | 320 640.00 |
| E PNT88000 TO TRANSFER PARTS & COMPONENTS TO NEW TAIL GATE | | | | | 380.00 |
| E PNT88000 TO REMOVE & REFIT REAR WINDSCREEN | | | | | 80 150.00 |
| E PNT88000 TO PERFORM WATER LEAK TEST | | | | | 120.00 |
| M SUNDRY SUPPLY AND APPLY WINDSCREEN SEALANT | | | | | 640.00 |
| E PNT88000 TO REMOVE & REFIT ELECTRONIC, PARTS, AND COMPONENT ON REAR BOOT COMPARTMENT TO FACILITATE THE REPAIR | | | | | 180 320.00 |
| M SUNDRY ANTI-RUST PROOFING | | | | | 180 320.00 |
| M SUNDRY APPLY BODY SEALANT ON AFFECTED AREA | | | | | 320 640.00 |
| E PNT88000 TO REMOVE & REFIT REAR SEAT BENCH | | | | | |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------|--|
| JONATHAN PETER LAU | Cust No/Name /JONATHAN PETER LAU |
| 24 ETTRICK TERRACE | Reg No/Reg Date SND3545M / 23/12/2021 |
| 01-01 FRANKEL ESTATE | Date In/Mileage / 0 |
| SINGAPORE 458587 | Chassis No KNANC81BMN6151996 |
| Contact No Mobile: 96688763 | Engine No D4HEMH705449 |
| | Make/Model KIA/CARNIVAL 2.2 A D SR G641 8 SEAT |
| | Colour/Trim ABP AURORA BLACK / GYT BLACK/GRAY |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|--|-------|-------------------|-------|--------------------------|--------|
| CSM00087 | Cash | 22/10/2024/ 15:55 | TLL | 1210/ Lim Teng Keat | 11536 |
| Description of Goods / Services | Qty | Unit Price | Disc% | Amount | |
| A 54900099 TO REMOVE & REFIT FUEL TANK | | | | 640.00 960.00 | X |
| A 54900099 TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | | | | 100 280.00 | |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM | | | | 380.00 | |
| M SUNDRY SUPPLY REAR LICENSE PLATE WITH CASING | | | | X 85.00 | |
| M SUNDRY C&C EMBLEM | | | | 50.00 | |
| M SUNDRY SUNDRIES | | | | 20.00 | |
| M COVER-RR BUMPER,UPR | 1.00 | 940.00 | 00.00 | 940.00 | / |
| M COVER-RR BUMPER LWR | 1.00 | 511.00 | 00.00 | 511.00 | / |
| M SKID PLATE-RR BUMPER | 1.00 | 452.00 | 00.00 | 452.00 | / |
| M COVER-RR BUMPER UNDER,LH | 1.00 | 33.00 | 00.00 | 33.00 | / |
| M LAMP ASSY-SIDE T/SIG & REAR,LH | 1.00 | 151.00 | 00.00 | 151.00 | / |
| M LAMP ASSY-SIDE T/SIG & REAR,RH | 1.00 | 151.00 | 00.00 | 151.00 | / |
| M ANTENNA ASSY-SMARTKEY | 1.00 | 45.00 | 00.00 | 45.00 | / |
| M WIRING HARNESS-RR BUMPER | 1.00 | 427.00 | 00.00 | 427.00 | / |
| M BEAM-RR BUMPER | 1.00 | 313.00 | 00.00 | 313.00 | / |
| M BRACKET-RR BEAM LWR MTG,LH | 1.00 | 37.00 | 00.00 | 37.00 | / |
| M BRACKET-RR BEAM LWR MTG,RH | 1.00 | 37.00 | 00.00 | 37.00 | / |
| M BRACKET-RR BUMPER RAIL LWR,LH | 1.00 | 37.00 | 00.00 | 37.00 | / |
| M BRACKET-RR BUMPER RAIL LWR,RH | 1.00 | 6.00 | 00.00 | 6.00 | / |
| M STAY-RR BUMPER LH | 1.00 | 67.00 | 00.00 | 67.00 | / |
| M STAY-RR BUMPER RH | 1.00 | 67.00 | 00.00 | 67.00 | / |
| M BRACKET ASSY-RR BUMPER SIDE,LH | 1.00 | 23.00 | 00.00 | 23.00 | / |
| M BRACKET ASSY-RR BUMPER SIDE,RH | 1.00 | 23.00 | 00.00 | 23.00 | / |
| M LAMP ASSY-REAR FOG | 1.00 | 133.00 | 00.00 | 133.00 | / |
| M PANEL ASSY-TAIL GATE | 1.00 | 2136.00 | 00.00 | 2136.00 | / |
| M HINGE ASSY-TAIL GATE,LH | 2.00 | 25.00 | 00.00 | 50.00 | / |
| M DRIVE UNIT ASSY-PWR T/GATE,LH | 1.00 | 853.00 | 00.00 | 853.00 | / |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|-------------------------------------|
| JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763 | Cust No/Name | /JONATHAN PETER LAU |
| | Reg No/Reg Date | SND3545M / 23/12/2021 |
| | Date In/Mileage | / 0 |
| | Chassis No | KNANC81BMN6151996 |
| | Engine No | D4HEMH705449 |
| | Make/Model | KIA/CARNIVAL 2.2 A D SR G641 8 SEAT |
| | Colour/Trim | ABP AURORA BLACK / GYT BLACK/GRAY |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|---------------------------------|---------------------------------|-------------------|------|---------------------|--------|------------|-------|---------|
| CSM00087 | Cash | 22/10/2024/ 15:55 | TLL | 1210/ Lim Teng Keat | 11536 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| M | DRIVE UNIT ASSY-PWR T/GATE, RH | ? | x nn | | 1.00 | 853.00 | 00.00 | 853.00 |
| M | TRIM ASSY-TAIL GATE LWR | de | | | 1.00 | 383.00 | 00.00 | 383.00 |
| M | W/STRIP-TAIL GATE OPNG | ? | x nn | | 1.00 | 130.00 | 00.00 | 130.00 |
| M | W/STRIP ASSY-T/GATE A/PINCH, LH | ? | x nn | | 1.00 | 223.00 | 00.00 | 223.00 |
| M | W/STRIP ASSY-T/GATE A/PINCH, RH | ? | x nn | | 1.00 | 223.00 | 00.00 | 223.00 |
| M | OUTSIDE HDL & LOCK ASSY-T/LID | de | | | 1.00 | 177.00 | 00.00 | 177.00 |
| M | GARNISH ASSY-TAIL GATE | ? | x nn | | 1.00 | 624.00 | 00.00 | 624.00 |
| M | SCREW-TAPPING | nn | | | 2.00 | 1.00 | 00.00 | 2.00 |
| M | SEALING PAD-B/PNL MLDG NO.2 | nn | | | 18.00 | 1.00 | 00.00 | 18.00 |
| M | CLIP-SIDE GARNISH MTG | nn | x nn | | 10.00 | 3.00 | 00.00 | 30.00 |
| M | T/SCREW-COUNTERSINK HEAD | nn | | | 8.00 | 1.00 | 00.00 | 8.00 |
| M | SEALING PAD-B/PNL MLDG NO.4 | nn | | | 2.00 | 1.00 | 00.00 | 2.00 |
| M | SEALING PAD-B/PNL MLDG NO.1 | nn | | | 2.00 | 4.00 | 00.00 | 8.00 |
| M | PAD-TAIL GATE GARNISH | nn | | | 2.00 | 2.00 | 00.00 | 4.00 |
| M | CAP NUT-RADIATOR, UPR | nn | | | 2.00 | 4.00 | 00.00 | 8.00 |
| M | SEALING PAD-B/PNL MLDG NO.3 | nn | | | 2.00 | 1.00 | 00.00 | 2.00 |
| M | EMBLEM-KIA | x nn | | | 1.00 | 54.00 | 00.00 | 54.00 |
| M | EMBLEM-CARNIVAL | nn | | | 1.00 | 89.00 | 00.00 | 89.00 |
| M | PANEL ASSY-BACK | nn | | | 1.00 | 633.00 | 00.00 | 633.00 |
| M | TRIM ASSY-RR TRANSVERSE | de | | | 1.00 | 99.00 | 00.00 | 99.00 |
| M | PAD-WINDSHIELD GLASS | nn | | | 14.00 | 2.00 | 00.00 | 28.00 |
| M | TERMINAL-RR WDO GLASS DEFOGGER | nn | | | 2.00 | 18.00 | 00.00 | 36.00 |
| P | STOPPER-TAIL GATE GLASS | nn | | | 2.00 | 3.00 | 00.00 | 6.00 |
| M | HOUSING-FUEL FILLER DR | x nn | | | 1.00 | 268.00 | 00.00 | 268.00 |
| M | LAMP ASSY-CENTER GARNISH | nn | | | 1.00 | 1910.00 | 00.00 | 1910.00 |
| M | GUARD ASSY-REAR WHEEL, LH | de | | | 1.00 | 193.00 | 00.00 | 193.00 |
| M | ULTRASONIC SENSOR-S.P.A.S | ? | x nn | | 4.00 | 177.00 | 00.00 | 708.00 |
| M | TRIM ASSY-TAIL GATE UPR | x nn | | | 1.00 | 44.00 | 00.00 | 44.00 |
| M | TRIM ASSY-TAIL GATE FRAME SIDE | x nn | | | 1.00 | 29.00 | 00.00 | 29.00 |
| M | TRIM ASSY-TAIL GATE FRAME SIDE | x nn | | | 1.00 | 29.00 | 00.00 | 29.00 |
| M | PAD-ANTINOISE | de | | | 10.00 | 1.00 | 00.00 | 10.00 |
| M | TRIM ASSY-LUGGAGE SIDE LH | de | | | 1.00 | 626.00 | 00.00 | 626.00 |
| M | TRIM ASSY-LUGGAGE SIDE RH | de | | | 1.00 | 670.00 | 00.00 | 670.00 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|-------------------------------------|
| JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763 | Cust No/Name | /JONATHAN PETER LAU |
| | Reg No/Reg Date | SND3545M / 23/12/2021 |
| | Date In/Mileage | / 0 |
| | Chassis No | KNANC81BMN6151996 |
| | Engine No | D4HEMH705449 |
| | Make/Model | KIA/CARNIVAL 2.2 A D SR G641 8 SEAT |
| | Colour/Trim | ABP AURORA BLACK / GYT BLACK/GRAY |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|---------------------------------|---------------------------------------|-------------------|------------|---------------------|---------|
| CSM00087 | Cash | 22/10/2024/ 15:55 | TLL | 1210/ Lim Teng Keat | 11536 |
| Description of Goods / Services | | Qty | Unit Price | Disc% | Amount |
| M | PANEL ASSY-REAR FLOOR,RR <i>bu</i> | 1.00 | 264.00 | 00.00 | 264.00 |
| M | PANEL ASSY-REAR FLOOR,FRT <i>X nn</i> | 1.00 | 498.00 | 00.00 | 498.00 |
| M | WIRING ASSY-FLOOR <i>x np</i> | 1.00 | 3974.00 | 00.00 | 3974.00 |
| M | CARPET ASSY-REAR FLOOR <i>de</i> | 1.00 | 449.00 | 00.00 | 449.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: *RASUL - Hy 90010068*SURVEYOR SIGNATURE: *Ru*DATE: *23/10/24*REMARKS: *16 --- 12 days**Res by paint*

Confirm & accepted by

| | |
|----------------------|------------------|
| Nett | 35,389.00 |
| 9% GST on 35389.00 | 3185.01 |
| Total Payable | 38,574.01 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Kia Carnival Diesel 2.2A Sunroof

\$199,888 Instalment \$1,747/mth

PREMIUM AD

Shortlist

Get Warranty

Loan Calculator



Overview Financial Photo Research

| | |
|--------------|---|
| Depreciation | \$25,840 / year |
| Reg. Date | 06-Aug-2021 (6yrs 9mths 12days COE left) |
| Manufactured | 2021 |
| Mileage | 51,888 km (16.1k / year) |
| Transmission | Auto |
| Engine Cap | 2,151 cc |
| Road Tax | \$2,052 / year |
| Power | 148.0 kW (198 bhp) View specs of the Kia Carnival Diesel (2021-2023) |
| Curb Weight | 2,187 kg |
| Fuel Type | Diesel (Euro 5 Engine and Above) |
| COE | \$56,032 |
| OMV | \$40,847 |
| ARF | \$49,186 |
| Dereg Value | \$74,899 as of today |

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|--|---------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 533A |
| Vehicle Details | |
| Vehicle No.: | SND3545M |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 24 Oct 2024 |
| Vehicle Make: | KIA |
| Vehicle Model: | CARNIVAL 2.2 DIESEL 8 SEATER SUNROOF |
| Primary Colour: | Black |
| Manufacturing Year: | 2021 |
| Engine No.: | D4HEMH705449 |
| Chassis No.: | KNANC81BMN6151996 |
| Maximum Power Output: | 148.0 kW (198 bhp) |
| Open Market Value: | \$39,753.00 |
| Original Registration Date: | 23 Dec 2021 |
| First Registration Date: | 23 Dec 2021 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$47,655.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 22 Dec 2031 |
| PARF Rebate Amount: | \$35,741.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 22 Dec 2031 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$58,089.00 |
| COE Rebate Amount: | \$41,586.00 |
| Total Rebate Amount: | \$77,327.00 |
| Message | |
| You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE. | |

The information contained herein is correct as at 24 Oct 2024

OK