

(08/11/13) WBT

ASS. REC. BY:

REF: CS/FCI 241 00396/XXP3 Eqp3

533A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SND 3545M

at Workshop m/s CYCLE & CARRIAGE

of PANDAN GARDEN

Insured: FCI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 207K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNO 3545M Yr Regn: 2021 1062

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA CARNIVAL 2.2 D18XRL 8S c.c 2151

Colour: BLACK AC: Insured / Std / NI / NA

Sp. Reading: 98761 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNANC61BMN 615 1996

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/35R17

R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 20/10/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT 129K

16/06/25 Finalised with Ms Loi final fig \$25956.98, 12 days (Red \$13688, 35%)

Date/Time, File Pass to?

☐

Prel. Report

1) 16/06 Typist

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: 12

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

Report Format: TP

Lump Sum F.I.B.I. (\$) 25956.98

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	/ 0
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
Z TEXT TP CLAIM COMFORT / DOA SUR OO REPAIR DAYS					4480 6400.00
E PNT88000 TO REPLACE REAR BUMPER, TAIL GATE, REAR END PANEL, REAR FLOOR PANEL, REAR LHS FENDER REPAIR ACCIDENT AFFECTED AREA					2750 3300.00
E PNT98000 PAINT WORK REAR BUMPER, TAIL GATE, REAR END PANEL, REAR LHS FENDER REAR FLOOR PANEL					600.00
E PNT88000 TO MOUNT VEHICLE ON FLOOR BENCH TO ALIGN CHASSIS					120 240.00
E PNT88000 TO REMOVE & REFIT REAR PARKING SENSOR					320 640.00
E PNT88000 TO TRANSFER PARTS & COMPONENTS TO NEW TAIL GATE					380.00
E PNT88000 TO REMOVE & REFIT REAR WINDSCREEN					80 150.00
E PNT88000 TO PERFORM WATER LEAK TEST					120.00
M SUNDRY SUPPLY AND APPLY WINDSCREEN SEALANT					640.00
E PNT88000 TO REMOVE & REFIT ELECTRONIC, PARTS, AND COMPONENT ON REAR BOOT COMPARTMENT TO FACILITATE THE REPAIR					180 320.00
M SUNDRY ANTI-RUST PROOFING					180 320.00
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREA					320 640.00
E PNT88000 TO REMOVE & REFIT REAR SEAT BENCH					

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
JONATHAN PETER LAU	Cust No/Name /JONATHAN PETER LAU
24 ETTRICK TERRACE	Reg No/Reg Date SND3545M / 23/12/2021
01-01 FRANKEL ESTATE	Date In/Mileage / 0
SINGAPORE 458587	Chassis No KNANC81BMN6151996
Contact No Mobile: 96688763	Engine No D4HEMH705449
	Make/Model KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A 54900099 TO REMOVE & REFIT FUEL TANK							X	640? 960.00
A 54900099 TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								100 280.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								380.00
M SUNDRY SUPPLY REAR LICENSE PLATE WITH CASING								X 85.00
M SUNDRY C&C EMBLEM								50.00
M SUNDRY SUNDRIES							nec	20 80.00
M COVER-RR BUMPER,UPR					1.00	940.00	00.00	940.00
M COVER-RR BUMPER LWR					1.00	511.00	00.00	511.00
M SKID PLATE-RR BUMPER					1.00	452.00	00.00	452.00
M COVER-RR BUMPER UNDER,LH					1.00	33.00	00.00	33.00
M LAMP ASSY-SIDE T/SIG & REAR,LH					1.00	151.00	00.00	151.00
M LAMP ASSY-SIDE T/SIG & REAR,RH					1.00	151.00	00.00	151.00
M ANTENNA ASSY-SMARTKEY					1.00	45.00	00.00	45.00
M WIRING HARNESS-RR BUMPER					1.00	427.00	00.00	427.00
M BEAM-RR BUMPER					1.00	313.00	00.00	313.00
M BRACKET-RR BEAM LWR MTG,LH					1.00	37.00	00.00	37.00
M BRACKET-RR BEAM LWR MTG,RH					1.00	37.00	00.00	37.00
M BRACKET-RR BUMPER RAIL LWR,LH					1.00	37.00	00.00	37.00
M BRACKET-RR BUMPER RAIL LWR,RH					1.00	6.00	00.00	6.00
M STAY-RR BUMPER LH					1.00	67.00	00.00	67.00
M STAY-RR BUMPER RH					1.00	67.00	00.00	67.00
M BRACKET ASSY-RR BUMPER SIDE,LH					1.00	23.00	00.00	23.00
M BRACKET ASSY-RR BUMPER SIDE,RH					1.00	23.00	00.00	23.00
M LAMP ASSY-REAR FOG					1.00	133.00	00.00	133.00
M PANEL ASSY-TAIL GATE					1.00	2136.00	00.00	2136.00
M HINGE ASSY-TAIL GATE,LH					2.00	25.00	00.00	50.00
M DRIVE UNIT ASSY-PWR T/GATE,LH					1.00	853.00	00.00	853.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	/ 0
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	DRIVE UNIT ASSY-PWR T/GATE, RH	?	x nn		1.00	853.00	00.00	853.00
M	TRIM ASSY-TAIL GATE LWR	de			1.00	383.00	00.00	383.00
M	W/STRIP-TAIL GATE OPNG	?	x nn		1.00	130.00	00.00	130.00
M	W/STRIP ASSY-T/GATE A/PINCH, LH	?	x nn		1.00	223.00	00.00	223.00
M	W/STRIP ASSY-T/GATE A/PINCH, RH	?	x nn		1.00	223.00	00.00	223.00
M	OUTSIDE HDL & LOCK ASSY-T/LID	de			1.00	177.00	00.00	177.00
M	GARNISH ASSY-TAIL GATE	?	x nn		1.00	624.00	00.00	624.00
M	SCREW-TAPPING	nn			2.00	1.00	00.00	2.00
M	SEALING PAD-B/PNL MLDG NO.2	nn			18.00	1.00	00.00	18.00
M	CLIP-SIDE GARNISH MTG	nn			10.00	3.00	00.00	30.00
M	T/SCREW-COUNTERSINK HEAD	nn			8.00	1.00	00.00	8.00
M	SEALING PAD-B/PNL MLDG NO.4	nn			2.00	1.00	00.00	2.00
M	SEALING PAD-B/PNL MLDG NO.1	nn			2.00	4.00	00.00	8.00
M	PAD-TAIL GATE GARNISH	nn			2.00	2.00	00.00	4.00
M	CAP NUT-RADIATOR, UPR	nn			2.00	4.00	00.00	8.00
M	SEALING PAD-B/PNL MLDG NO.3	nn			2.00	1.00	00.00	2.00
M	EMBLEM-KIA	x nn			1.00	54.00	00.00	54.00
M	EMBLEM-CARNIVAL	nn			1.00	89.00	00.00	89.00
M	PANEL ASSY-BACK	nn			1.00	633.00	00.00	633.00
M	TRIM ASSY-RR TRANSVERSE	de			1.00	99.00	00.00	99.00
M	PAD-WINDSHIELD GLASS	nn			14.00	2.00	00.00	28.00
M	TERMINAL-RR WDO GLASS DEFOGGER	nn			2.00	18.00	00.00	36.00
P	STOPPER-TAIL GATE GLASS	nn			2.00	3.00	00.00	6.00
M	HOUSING-FUEL FILLER DR	x nn			1.00	268.00	00.00	268.00
M	LAMP ASSY-CENTER GARNISH	nn			1.00	1910.00	00.00	1910.00
M	GUARD ASSY-REAR WHEEL, LH	de			1.00	193.00	00.00	193.00
M	ULTRASONIC SENSOR-S.P.A.S	x nn			4.00	177.00	00.00	708.00
M	TRIM ASSY-TAIL GATE UPR	x nn			1.00	44.00	00.00	44.00
M	TRIM ASSY-TAIL GATE FRAME SIDE	x nn			1.00	29.00	00.00	29.00
M	TRIM ASSY-TAIL GATE FRAME SIDE	x nn			1.00	29.00	00.00	29.00
M	PAD-ANTINOISE	de			10.00	1.00	00.00	10.00
M	TRIM ASSY-LUGGAGE SIDE LH	de			1.00	626.00	00.00	626.00
M	TRIM ASSY-LUGGAGE SIDE RH	de			1.00	670.00	00.00	670.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	/ 0
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	PANEL ASSY-REAR FLOOR,RR <i>bu</i>	1.00	264.00	00.00	264.00
M	PANEL ASSY-REAR FLOOR,FRT <i>Xnn</i>	1.00	498.00	00.00	498.00
M	WIRING ASSY-FLOOR <i>x nn</i>	1.00	3974.00	00.00	3974.00
M	CARPET ASSY-REAR FLOOR <i>de</i>	1.00	449.00	00.00	449.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: *RASUL - Hy 90010068*SURVEYOR SIGNATURE: *Ru*DATE: *23/10/24*REMARKS: *12 days**Res by paint*

Confirm & accepted by

Nett	35,389.00
9% GST on	35389.00
	3185.01
Total Payable	38,574.01

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Kia Carnival Diesel 2.2A Sunroof

\$199,888 Instalment \$1,747/mth

PREMIUM AD

Shortlist

Get Warranty

Loan Calculator



Overview Financial Photo Research

Depreciation	\$25,840 / year
Reg. Date	06-Aug-2021 (6yrs 9mths 12days COE left)
Manufactured	2021
Mileage	51,888 km (16.1k / year)
Transmission	Auto
Engine Cap	2,151 cc
Road Tax	\$2,052 / year
Power	148.0 kW (198 bhp) View specs of the Kia Carnival Diesel (2021-2023)
Curb Weight	2,187 kg
Fuel Type	Diesel (Euro 5 Engine and Above)
COE	\$56,032
OMV	\$40,847
ARF	\$49,186
Dereg Value	\$74,899 as of today

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	533A
Vehicle Details	
Vehicle No.:	SND3545M
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2024
Vehicle Make:	KIA
Vehicle Model:	CARNIVAL 2.2 DIESEL 8 SEATER SUNROOF
Primary Colour:	Black
Manufacturing Year:	2021
Engine No.:	D4HEMH705449
Chassis No.:	KNANC81BMN6151996
Maximum Power Output:	148.0 kW (198 bhp)
Open Market Value:	\$39,753.00
Original Registration Date:	23 Dec 2021
First Registration Date:	23 Dec 2021
Transfer Count:	0
Actual ARF Paid:	\$47,655.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2031
PARF Rebate Amount:	\$35,741.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,089.00
COE Rebate Amount:	\$41,586.00
Total Rebate Amount:	\$77,327.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 24 Oct 2024

OK