

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763 24/10/	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	17/12/2024/ 98161
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00087	Cash	08/03/2025/ 17:13	TLL	1210/ Lim Teng Keat	11536		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
Z TEXT							
TP CLAIM MS FIRST CAP							
DOA 20/10/2024							
SUR LKK RASUL							
12 REPAIR DAYS							
E PNT88000							4480.00
TO REPLACE REAR BUMPER, TAIL GATE, REAR END PANEL,							
REAR FLOOR PANEL, REAR LHS FENDER							
REPAIR ACCIDENT AFFECTED AREA							
E PNT98000							2750.00
PAINT WORK REAR BUMPER, TAIL GATE, REAR END PANEL, REAR LHS FENDER,							
REAR FLOOR PANEL							
E PNT88000							600.00
TO MOUNT VEHICLE ON FLOOR BENCH TO ALIGN CHASSIS							
E PNT88000							120.00
TO REMOVE & REFIT REAR PARKING SENSOR							
E PNT88000							320.00
TO TANSFER PARTS & COMPONENTS TO NEW TAIL GATE							
E PNT88000							380.00
TO REMOVE & REFIT REAR WINDSCREEN							
E PNT88000							80.00
TO PERFORM WATER LEAK TEST							
M SUNDRY							120.00
SUPPLY AND APPLY WINDSCREEN SEALANT							
E PNT88000							640.00
TO REMOVE & REFIT ELECTRONIC, PARTS, AND COMPONENT ON REAR BOOT							
COMPARTMENT TO FACILITATE THE REPAIR							
M SUNDRY							180.00
ANTI-RUST PROOFING							
M SUNDRY							180.00
APPLY BODY SEALANT ON AFFECTED AREA							
E PNT88000							320.00
TO REMOVE & REFIT REAR SEAT BENCH							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763 24/10/	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	17/12/2024/ 98161
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00087	Cash	08/03/2025/ 17:13	TLL	1210/ Lim Teng Keat	11536		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
A 54900099							100.00
TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							380.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							50.00
C&C EMBLEM							
M SUNDRY							20.00
SUNDRIES							
A 10028901							380.00
CALIBRATION REAR RADAR UNIT SYSTEM							
A 97000001							640.00
REMOVE AND INSTALL REAR AIRCON UNIT TO FACILITATE							
REPAIR WORK							
A 97000001							100.00
TOP UP A/CON GAS -- RR A/CON							
X	COVER-RR BUMPER,UPR			1.00	940.00	00.00	940.00
X	COVER-RR BUMPER LWR			1.00	511.00	00.00	511.00
X	SKID PLATE-RR BUMPER			1.00	452.00	00.00	452.00
X	COVER-RR BUMPER UNDER,LH			1.00	33.00	00.00	33.00
X	LAMP ASSY-SIDE T/SIG & REAR,LH			1.00	151.00	00.00	151.00
X	BEAM-RR BUMPER			1.00	313.00	00.00	313.00
X	BRACKET-RR BEAM LWR MTG,LH			1.00	37.00	00.00	37.00
X	BRACKET-RR BEAM LWR MTG,RH			1.00	37.00	00.00	37.00
X	LAMP ASSY-REAR FOG			1.00	133.00	00.00	133.00
X	PANEL ASSY-TAIL GATE			1.00	2136.00	00.00	2136.00
X	TRIM ASSY-TAIL GATE LWR			1.00	383.00	00.00	383.00
X	OUTSIDE HDL & LOCK ASSY-T/LID			1.00	177.00	00.00	177.00
X	SCREW-TAPPING			2.00	1.00	00.00	2.00
X	SEALING PAD-B/PNL MLDG NO.2			18.00	1.00	00.00	18.00
X	T/SCREW-COUNTERSINK HEAD			8.00	1.00	00.00	8.00
X	SEALING PAD-B/PNL MLDG NO.4			2.00	1.00	00.00	2.00
X	SEALING PAD-B/PNL MLDG NO.1			2.00	4.00	00.00	8.00
X	PAD-TAIL GATE GARNISH			2.00	2.00	00.00	4.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU 24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587 Contact No Mobile: 96688763 24/10/	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	17/12/2024/ 98161
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	08/03/2025/ 17:13	TLL	1210/ Lim Teng Keat	11536
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X CAP NUT-RADIATOR,UPR		2.00	4.00	00.00	8.00
X SEALING PAD-B/PNL MLDG NO.3		2.00	1.00	00.00	2.00
X EMBLEM-CARNIVAL		1.00	89.00	00.00	89.00
X PANEL ASSY-BACK		1.00	633.00	00.00	633.00
X TRIM ASSY-RR TRANSVERSE		1.00	99.00	00.00	99.00
X PAD-WINDSHIELD GLASS		14.00	2.00	00.00	28.00
X TERMINAL-RR WDO GLASS DEFOGGER		2.00	18.00	00.00	36.00
X STOPPER-TAIL GATE GLASS		2.00	3.00	00.00	6.00
X LAMP ASSY-CENTER GARNISH		1.00	1910.00	00.00	1910.00
X GUARD ASSY-REAR WHEEL,LH		1.00	193.00	00.00	193.00
X PAD-ANTINOISE		10.00	1.00	00.00	10.00
X TRIM ASSY-LUGGAGE SIDE LH		1.00	626.00	00.00	626.00
X TRIM ASSY-LUGGAGE SIDE RH		1.00	670.00	00.00	670.00
M PANEL ASSY-REAR FLOOR,RR		1.00	264.00	00.00	264.00
X CARPET ASSY-REAR FLOOR		1.00	449.00	00.00	449.00
X COVER ASSY-SHIELD INR,RH		1.00	18.00	00.00	18.00
X FRAME ASSY-3RD SEAT CUSH,RH		1.00	1114.00	00.00	1114.00
X SILENCER,FLOOR		2.00	13.00	00.00	26.00
X PANEL ASSY-RR FLOOR SIDE,LH		1.00	57.00	00.00	57.00
X CLIP-SIDE GARNISH MTG		10.00	3.00	00.00	30.00
X BRACKET-RR BUMPER RAIL LWR,RH		1.00	6.00	00.00	6.00
X BRACKET ASSY-RR BUMPER SIDE,RH		1.00	23.00	00.00	23.00
X BRACKET ASSY-RR BUMPER SIDE,LH		1.00	23.00	00.00	23.00
X BRACKET-RR BUMPER RAIL LWR,LH		1.00	37.00	00.00	37.00
X PANEL ASSY-REAR FLOOR		1.00	1241.00	00.00	1241.00
X WIRING HARNESS-RR BUMPER		1.00	427.00	00.00	427.00
X STAY-RR BUMPER LH		1.00	67.00	00.00	67.00
X ULTRASONIC SENSOR-S.P.A.S		1.00	244.00	00.00	244.00
X BRACKET-RR BUMPER RAIL LWR,LH		1.00	37.00	00.00	37.00
X ANTIFREEZER @ 4 LITRE		1.00	108.98	00.00	108.98
M LEG ASSY-3RD,RH		1.00	290.00	00.00	290.00

Confirm & accepted by

Nett	25,956.98
9% GST on	25956.98
Total Payable	28,293.11

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.