



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU  24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587  <b>Contact No</b> Mobile: 96688763 24/10/	<b>Cust No/Name</b>	/JONATHAN PETER LAU
	<b>Reg No/Reg Date</b>	SND3545M / 23/12/2021
	<b>Date In/Mileage</b>	17/12/2024/ 98161
	<b>Chassis No</b>	KNANC81BMN6151996
	<b>Engine No</b>	D4HEMH705449
	<b>Make/Model</b>	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	<b>Colour/Trim</b>	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	08/03/2025/ 17:13	TLL	1210/ Lim Teng Keat	11536

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A 10028901 CALIBRATION REAR RADAR UNIT SYSTEM				380.00 /
A 97000001 REMOVE AND INSTALL REAR AIRCON UNIT TO FACILITATE REPAIR WORK				640.00 /
A 97000001 TOP UP A/CON GAS -- RR A/CON				100.00 /
X COVER ASSY-SHIELD INR,RH	1.00	18.00	00.00	BR 18.00 /
X FRAME ASSY-3RD SEAT CUSH,RH	1.00	1114.00	00.00	BT 1114.00 /
X SILENCER,FLOOR	2.00	13.00	00.00	Nec 26.00 /
X PANEL ASSY-RR FLOOR SIDE,LH	1.00	57.00	00.00	DD 57.00 /
X CLIP-SIDE GARNISH MTG	10.00	3.00	00.00	Nec 30.00 /
X BRACKET-RR BUMPER RAIL LWR,RH	1.00	6.00	00.00	Nec 6.00 /
X BRACKET ASSY-RR BUMPER SIDE,RH	1.00	23.00	00.00	BR 23.00 /
X BRACKET ASSY-RR BUMPER SIDE,LH	1.00	23.00	00.00	BR 23.00 /
X BRACKET-RR BUMPER RAIL LWR,LH	1.00	37.00	00.00	MIS 37.00 /
X PANEL ASSY-REAR FLOOR	1.00	1241.00	00.00	DD 1241.00 /
X WIRING HARNESS-RR BUMPER	1.00	427.00	00.00	TN 427.00 /
X STAY-RR BUMPER LH	1.00	67.00	00.00	BR 67.00 /
X ULTRASONIC SENSOR-S.P.A.S	1.00	244.00	00.00	BR 244.00 /
X BRACKET-RR BUMPER RAIL LWR,LH	1.00	37.00	00.00	MIS 37.00 /
X ANTIFREEZER @ 4 LITRE	1.00	108.98	00.00	Nec 108.98 /
M LEG ASSY-3RD,RH	1.00	290.00	00.00	BR 290.00 /

Confirm &amp; accepted by

9% GST on	Nett 4868.98	4,868.98 438.21
<b>Total Payable</b>		<b>5,307.19</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.