

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@proccarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

LONPAC INSURANCE BHD

300 Beach Road #17-04/07
The Concourse Singapore 199555

Attn: Motor Claim Department

Your Ref No: TP 1024-8317
Claim Type: Third Party
Accident Date: 21 October 2024
TP Veh Reg No: GBK5742C

Estimate No: EST1511951

Date: 22 Oct 2024

Policy No: SP2005168648

Veh Reg No: SGW60Y

Make/Model: MERCEDES BENZ

S320L (R19 LED)

WDD2221622A258905

Engine No: 27682430366110

Reg. Date: 16 Aug 2016

Estimate Repair Cost to Vehicle No: SGW60Y

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER (UPPER) <i>(u)/Torn</i>	2,635.00	1 PC	2,635.00 ✓	
2 REAR BUMPER SIDE RETAINER - LH/RH <i>u</i>	78.00	2 PC	156.00 X	
3 REAR BUMPER RIVET <i>u</i>	9.00	10 PC	90.00 ✓	
4 REAR BUMPER (LOWER TRIM) <i>u</i>	585.00	1 PC	585.00 X	
5 REAR BUMPER REFLECTOR - LH <i>u</i>	35.00	1 PC	35.00 X	
6 REAR BUMPER REINFORCEMENT <i>u</i>	1,640.00	1 PC	1,640.00 X	
7 REAR BUMPER SIDE CHROME MOULDING - <i>cre u/s</i> LH/RH	156.00	2 PC	312.00 <i>1pc</i>	
8 REAR EXHAUST CHROME - LH <i>u</i>	950.00	1 PC	950.00 X	
9 REAR BUMPER SENSOR (OUTER) - LH <i>u</i>	215.00	1 PC	215.00 X	
10 REAR BUMPER SENSOR (INNER) - LH <i>u</i>	215.00	1 PC	215.00 X	
11 REAR BUMPER SENSOR RING <i>u</i>	14.00	4 PC	56.00 ✓	
12 TAIL LAMP - LH <i>cre</i>	1,285.00	1 PC	1,285.00 ✓	
13 TAIL LAMP LOWER RETAINER - LH <i>cre</i>	130.00	1 PC	130.00 ✓	
			8,304.00	
		Less 10%	-830.40	7,473.60
Labour				
14 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PORTIONS-	600.00	1 JOB	600.00 <i>300</i>	
15 TO RESPRAY PAINT ON ACCIDENT PORTIONS-	550.00	1 JOB	550.00 <i>400</i>	
16 TO CHECK WIRING-	30.00	1 JOB	30.00 <i>20</i>	
17 TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	150.00	1 JOB	150.00 <i>u</i>	
18 TO REMOVE, REPLACE REAR BUMPER SENSOR-	80.00	1 JOB	80.00 <i>30</i>	
19 TO RESET REAR SENSOR & OTHER NEC CHECKLIGHT-	200.00	1 JOB	200.00 <i>u</i>	
				1,610.00
				<i>750</i>

SINGAPORE DOLLAR NINE THOUSAND NINE HUNDRED ONE AND CENTS TWELVE ONLY

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total 9,083.60
Add GST @ 9% 817.52
Total Amount Payable SGD 9,901.12

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE