



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGC7391B

Great Eastern General Insurance
Limited
Motor Claim Department
1 Pickering Street
#10-01 Great Eastern Centre
Singapore 048659
62482638

Vehicle & Document Information

WIP No **21623**
Reg No/Reg Date **SGC7391B / 27/03/2020**
Date In/Mileage **28/10/2024/ 114623**
Chassis No **W1N2539802F7621968**
Engine No **26492030244684**
Make/Model **MB/GLC 200**
Colour/Trim **029 992 Selenite Gr/ 041 101 ARTICO Blac**

Account No	Terms	Date/Time Printed	CSE	Operator				
W0000666	Credit	04/04/2025/ 16:00	SJ	1208/ Foong Shiuh Jye				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
*ACCIDENT TOW IN, RAN OVER SOMETHING ON THE ROAD								
M BPNSUN								
POLICY NO/ACC DATE : MOMVP000005236-01-000 // 19 OCT 2024								
TOW IN/EXCESS : 19 OCT 2024 // \$700								
DATE IN/DATE SURVEY: 23-10-2024 // RASUL - LKK								
BY/AUTHORIZED ON : 25-10-2024 // HUEY YON - LKK								
A BPILAB								1920.00
REMOVE CARRIAGE ASSY FROM FRAME, IMPACT.REPLACE AND ASSEMBLE								
A BPILAB								540.00
TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								
A BPILAB							0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO								
M BPNSUN								15.00
SUNDRIES								
X BPNEXC								-700.00
INSURANCE EXCESS								
S BPNTOW								150.00
ACCIDENT TOWING FROM 333 BOON LAY WAY TO PLSC								
USING KING DOLLEY AT MULTI CARPARK - B1.								
DO NO:1365685								
X OIL SUMP					1.00	553.54	00.00	553.54
X TRANSMISSION FLUID					2.00	240.35	00.00	480.70
X COVER, ENGINE COMP. LOWER					1.00	224.17	00.00	224.17
X COVER F ENGINE COMP. BM					1.00	281.56	00.00	281.56
X BUMPER FRONT UNDERNEATH COVER					1.00	265.82	00.00	265.82
X MOUNT Jack to integral carrier					1.00	45.93	00.00	45.93
X SCREW W RND. HEXAL. HEAD					10.00	5.25	00.00	52.50

Confirmed & accepted by

Nett **4,209.22**
9% GST on **4209.22** **378.83**

Authorized signatory and company stamp

Total Payable **4,588.05**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg