

(08/11/13) W&F  
ASS. REC. BY:

REF: CS/GAI24100402/RAP3


8942

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
 OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV  
To Inspect Vehicle No: SAC7391B  
at Workshop m/s Cycle & Carriage  
of PANDAN LOOP  
Insured: GAI  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: TBA  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 163K  
IDAC Accident Rpt: Consistent?: Yes or No  
GIA / PR Seen: Consistent?: Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA /  REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SAC7391B Yr Regn: 2020 / MAR  
Type:  M.Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /  Truck /  Trailer or  
Make: MERCEDES BENZ GLC 200 c.c. 1991  
Colour: GRAY A/C:  Insured /  Std /  NI /  NA  
Sp. Reading: 114624 T/Radio:  Insured /  Std /  NI /  NA  
Eng/No: \_\_\_\_\_  
C/No: W1N2539802F762196  
Gen. Cond:  Good /  Fair /  Poor /  Burnt  
Steering:  Inorder /  Jammed /  Leaked /  Burnt or  
Brake:  Inorder /  Jammed /  Leaked /  Burnt or  
Modi:  Nil /  S/Rim /  STD A/Rim or  
Tyre Size: F: 235/60R18  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or LAUFENN  
Front R/Bal. 6 mm L/Bal. 6 mm  
Rear R/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 19/10/24 D.O.I. 23/10/24  
Survey held at PANDAN LOOP  
Des. of Damages: Frt / Rear / O/S / N/S /  UIC / Rooftop or  
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
REPAIR LIMIT 10/K

Date/Time, File Pass to?

: Preli. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Date/Time, File Return to?

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

) S+RS \$ \_\_\_\_\_

) Photos \_\_\_\_\_

) Others \_\_\_\_\_

Report Format :

Lump Sum / I.B.I. (\$ \_\_\_\_\_)

TOTAL

Empty box for additional notes or calculations.



Mercedes-Benz

Cycle & Carriage Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

ESTIMATE FOR SGC7391B

Chieng King Wu

73 Choa Chu Kang Loop  
#11-05  
Singapore 689674

Mobile: +6596726713

Vehicle & Document Information

WIP No **21623**  
Reg No/Reg Date **SGC7391B / 27/03/2020**  
Date In/Mileage **0**  
Chassis No **W1N2539802F7621968**  
Engine No **26492030244684**  
Make/Model **MB/GLC 200**  
Colour/Trim **029 992 Selenite Gr/ 041 101 ARTICO Blac**

**SGC7391B**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	22/10/2024/ 17:49	SJ	1208/ Foong Shiuh Jye

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request *ACCIDENT TOW IN, RAN OVER SOMETHING ON THE ROAD				
M BPNSUN POLICY NO/ACC DATE : MOMVP000005236-01-000 // 19 OCT 2024 TOW IN/EXCESS : 19 OCT 2024 // TBA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB REMOVE CARRIAGE ASSY FROM FRAME, IMPACT.REPLACE AND ASSEMBLE				1920 <del>2400.00</del>
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO			0.10	380.00
M BPNSUN SUNDRIES				15.00
A BPILAB TOWING <i>invoice</i>				150.00
M OIL PAN <i>cm</i>	1.00	553.54	00.00	553.54
M ELASTOMERIC MOLDED SEAL <i>cm</i>	1.00	56.39	00.00	56.39
M TRANSMISSION FLUID <i>cm</i>	2.00	240.35	00.00	480.70
M COVER, ENGINE COMP. LOWER <i>cm</i>	1.00	224.17	00.00	224.17
M COVER F ENGINE COMP. BM <i>cm</i>	1.00	281.56	00.00	281.56
M AUTOMATIC TRANSMISSION <i>7</i>	1.00	21271.67	00.00	21271.67

**THIS IS NOT AN OFFICIAL TAX INVOICE**  
*Pass*  
*HP 900/10/08*  
*3 days*  
*23/10/24*  
*EXCESS: TDA*  
*Revert*  
*Reg after repair*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Confirmed & accepted by

Authorized signatory and company stamp

Nett **26,353.03**  
9% GST on **26353.03** **2371.77**  
**Total Payable 28,724.80**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



## Mercedes-Benz GLC-Class GLC200


**\$163,800** Instalment \$1,763/mth

PREMIUM AD

Apply for 2.48% loan

Shortlist

Get Warranty



### Overview Financial Photo Research

Depreciation	\$25,410 / year
Reg. Date	05-Mar-2020 (5yrs 4mths 9days COE left)
Manufactured	2019
Mileage	41,000 km (8.8k / year)
Transmission	Auto
Engine Cap	1,991 cc
Road Tax	\$1,202 / year
Power	145.0 kW (194 bhp) <a href="#">View specs of the Mercedes-Benz GLC-Class (2016-2023)</a>
Curb Weight	1,730 kg
COE	\$37,705
OMV	\$44,949
ARF	\$54,929
Dereg Value	\$61,423 as of today
No. of Owners	1

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	894Z
<b>Vehicle Details</b>	
Vehicle No.:	SGC7391B
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLC200 (R18 LED)
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	26492030244684
Chassis No.:	W1N2539802F762196
Maximum Power Output:	145.0 kW (194 bhp)
Open Market Value:	\$44,949.00
Original Registration Date:	27 Mar 2020
First Registration Date:	27 Mar 2020
Transfer Count:	0
Actual ARF Paid:	\$54,929.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Mar 2030
PARF Rebate Amount:	\$41,196.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Mar 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,705.00
COE Rebate Amount:	\$20,453.00
<b>Total Rebate Amount:</b>	<b>\$61,649.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 23 Oct 2024

OK