

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24100405/KPA3Q2  
Date: 14/11/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571\_01  
Claimant Vehicle No : SMZ1054Y Insured Vehicle No : SLK6922A  
Date of Loss: 15/10/2024 Nature of Claim: TP Claim No: MFL2024D0012513

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMZ1054Y  
Make & Model: MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A) Engine No: 27091031843097  
Reg. Date: 25/04/2019 (Man. Year: 2019) Chassis No: WDC1569422J604808  
Colour: Metallic Silver Odometer: 90011 km  
Engine Capacity: 1595 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18  
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 9 mm  
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,833.90	4,081.50	752.40	15.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,870.00	2,010.00	860.00	29.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	7,703.90	6,091.50	1,612.40	20.93

INSPECTION

Date of Assignment: 23/10/2024  
Date Inspected: 23/10/2024 Inspected At: Tong Luck Auto Pte Ltd (HQ)  
160 Sin Ming Drive, #07-01 Sin Ming AutoCity  
Singapore 575722  
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2024)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ1054Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER-RH	Bent / Warped	1,068.00 FN	*1,068.00 FN
2	1		*FRONT FENDER WHEEL ARCH GARNISH-RH	Cut	288.00 FN	*288.00 FN
3	1		*FRONT DOOR RH	Bent	2,230.00 FN	*2,230.00 FN
4	1		*FRONT DOOR WEATHERSTRIP-RH	Necessary	360.00 FN	*360.00 FN
5	20		*FRONT DOOR TRIMBOARD RIVET-RH	Necessary	240.00 FN	*240.00 FN
6	1		*REAR DOOR STICKER-RH	Necessary	44.00 FN	*44.00 FN
7	1		*REAR FENDER WHEEL ARCH GARNISH-RH	Scratched	305.00 FN	*305.00 FN
8	1		*FRONT SPORT RIM RH	Repair	836.00 FN	*- FN
					Sub Total (S\$)	5,371.00 4,535.00
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	537.10 453.50
					Total Parts (S\$)	4,833.90 4,081.50

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER RH FRONT DOOR INTERIOR MECHANISM & GLASS TO NEW DOOR	New	150.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEATING RH REAR DOOR ,RH CENTRE PILLAR ,RH FRONT FENDER INNER PANEL INCLUDING REPLACEMENT OF PARTS AND ALIGN WHEN NECESSARY TO REFIT AND ADJUST THE SAME	New	1,200.00	1,200.00
4	TO PUTTY ANS SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	550.00
5	TO COMPUTERISE WHEEL ALIGNMENT	New	120.00	60.00
6	TO APPLY RUST PROOFING ON REPLACED & REPAIRED PANELS	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,870.00</b>	<b>2,010.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >