



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722  
Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1  
1 GATEWAY DRIVE #15-08  
WESTGATE TOWER  
SINGAPORE 608531

TEL :  
ATTN : ACCOUNTS DEPT

YOUR REF NO : SLK6922A  
CLAIM TYPE : THIRD PARTY  
TP INS. CO. : INDIA INTERNATIONAL INSURANCE PTE LTD  
ACCIDENT DATE : 15/10/2024  
TP VEH REG NO : SLK6922A

## ESTIMATE

NO : QUOT202410-000044(00)  
DATE : 22/10/2024  
POLICY NO : SP2003907937  
VEH REG NO : SMZ1054Y  
MAKE/MODEL : MERCEDES BENZ GLA180  
URBAN (R18 LED)  
CHASSIS NO : WDC1569422J604808  
ENGINE NO : 27091031843097  
REG. DATE : 2019

PAGE: 1

## Estimate Repair Cost to Vehicle No : SMZ1054Y

| Description                                                                                                                                                         | Quantity | Unit Price | Amount   |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|----------|
|                                                                                                                                                                     |          | S\$        | S\$      |
| <b>NET PRICE</b>                                                                                                                                                    |          |            |          |
| 1 Front fender - RH                                                                                                                                                 | 1        | 1,068.00   | 1,068.00 |
| 2 Front fender wheel arch garnish - RH                                                                                                                              | 1        | 288.00     | 288.00   |
| 3 Front door - RH                                                                                                                                                   | 1        | 2,230.00   | 2,230.00 |
| 4 Front door weatherstrip - RH                                                                                                                                      | 1        | 360.00     | 360.00   |
| 5 Front door trimboard rivet - RH                                                                                                                                   | 20       | 12.00      | 240.00   |
| 6 Rear door sticker - RH                                                                                                                                            | 1        | 44.00      | 44.00    |
| 7 Rear fender wheel arch garnish - RH                                                                                                                               | 1        | 305.00     | 305.00   |
| 8 Front sport rim - RH                                                                                                                                              | 1        | 836.00     | 836.00   |
|                                                                                                                                                                     |          |            | 5,371.00 |
| Less 10%                                                                                                                                                            |          |            | 537.10   |
|                                                                                                                                                                     |          |            | 4,833.90 |
| <b>LABOUR</b>                                                                                                                                                       |          |            |          |
| 9 To transfer RH front door interior mechanism & glass to new door                                                                                                  | 1        | 150.00     | 150.00   |
| 10 To check and rectify wiring system                                                                                                                               | 1        | 80.00      | 80.00    |
| 11 To panel beat RH rear door, RH centre pillar, RH front fender inner panel, including replacement of parts and align when necessary, to refit and adjust the same | 1        | 1,200.00   | 1,200.00 |
| 12 To putty and spray paint on the affected areas                                                                                                                   | 1        | 1,200.00   | 1,200.00 |
| 13 To computerise check wheel alignment                                                                                                                             | 1        | 120.00     | 120.00   |
| 14 To apply rust-proofing on replaced & repaired panels                                                                                                             | 1        | 120.00     | 120.00   |
|                                                                                                                                                                     |          |            | 2,870.00 |

TOTAL S\$ 7,703.90

ADD GST @ 9.00% 693.36

GRAND TOTAL S\$ 8,397.26

SINGAPORE DOLLAR EIGHT THOUSAND THREE HUNDRED NINETY-SEVEN AND CENTS TWENTY-SIX ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE