

## Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/06/2024 User ID : PohSuan

Section A - Accident Details					
Registration Number	SHF253K				
Case Reference Number	TAX/06/24/2010				
Registration Date	14/Dec/2017				
Company Type	Strides Premier Taxi Pte Ltd				
Make	ТОУОТА				
Model	PRIUS4				
Name of Driver	HWEE MING SIANG ( WEI MINGXIANG )				
Type of Accident	Head to Rear				
Accident Date and Time	3/Jun/2024 6:25 PM				
Accident Reported Date and Time	4/Jun/2024 4:30 PM				
Is Surveyor Required?	Yes				
Survey by					
Vehicle is Towed Back?	No				
Towed Back Date and Time					
Replacement Vehicle issued?	No				
Job Card Number	24121544				
Special Instruction to ARC,if	TP/ REAR PORTION/TOS/AIG - LKK				
any Prepared Date and Time	11/Jun/2024 10:52 AM				
Chassis Number					
Mileage					
Work Shop					
Repair Completion Date and Time					

	Section B - Summary of Repair Estimates								
Summary of Repair Estimates									
	Quotation from ARC	Adjusted by Surveyor, if applicable							
Total Labour Cost	\$845.00	\$200.00							
Total Spray Cost	\$1,478.00	\$200.00							
Total Spare Part Cost	\$4,391.54	\$374.10							
Total Other Cost	\$500.00	\$30.00							
TOTAL COST	\$7,214.54	\$804.10							
Lump Sum Total	\$7,200.00	\$800.00 (L/S)							
Number of Repair Days	7.0	2.0							
Prepared / Adjusted By	Boon Chew Tay	Taufikh (LKK) / AIG							
ARC / Surveyor Sign Off Date	12/06/2024 5:25 PM	11/06/2024 5:20 PM							
Signature		Tausikh							
Remarks		L/S REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR TAUFIKH (LKK) / HP : 9749 5749 / Email taufikh@lkkauto.com							



## Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/06/2024
User ID : PohSuan

Section C - Quotation and Accident Invoice Details							
Quotation Number	QN-2406-0165	Invoice Number					
Quotation Date	14.06.2024	Invoice Date					
Invoice Amount		Prepared Date					

Section D - Details of Repair Estimates							
Part 1 - Labour Works							
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable					
TO REPAIR REAR PORTION	\$845.00	\$200.00					
Total Labour	\$845.00	\$200.00					

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO RESPRAY BUMPER BEAM	\$220.00	\$0.00		
TO RESPRAY REAR BUMPER	\$378.00	\$200.00		
TO RESPRAY REAR PANEL	\$220.00	\$0.00		
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00	\$0.00		
TO RESPRAY FILLER RR BUMPER LH	\$220.00	\$0.00		
TO RESPRAY FILLER RR BUMPER RH	\$220.00	\$0.00		
Fotal Spray Painting & Panel Beating	\$1,478.00	\$200.00		

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO WASH AND VACUUM	\$60.00	\$0.00		
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00		
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00		
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00		
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00		
Total Other Costs	\$500.00	\$30.00		

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52161160 10	CLIPS PIECE, FRT BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
		76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$992.30	0.00	\$0.00	Replace	Not Given	X
		75441470 90	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	0.00	\$59.10	0.00	\$0.00	Replace	Not Given	X
		75442471 30	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	0.00	\$59.10	0.00	\$0.00	Replace	Not Given	X
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	Replace	7
		52565479 00	FILLER, RR BUMPER , RH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	
		52566479	FILLER, RR BUMPER , LH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given	



## Strides Premier Accident Vehicle Repair Estimates

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated : 14/06/2024 User ID : PohSuan

al	40			\$7,171.20		\$467.63			^
		SEAL, RR BUMPER , LH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given	-
	40 52591470	SEAL, RR BUMPER , RH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given	-X
		RETAINER, RR BUMPER, LH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given	X
	40	,		· ·					X
		RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given	
	52599680 30	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
	30	& LH							X
	10 52191470	SEAL, RR BUMPER ARM, RH	0.00	\$12.30	0.00	\$0.00	Replace	Not Given	
	52461470	PAD, RR BUMPER, CTR	0.00	\$2.50	0.00	\$0.00	Replace	Not Given	-X
	52462470 10	PAD, RR BUMPER, RH & LH ,	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	X
	20	2	0.00	04.00	0.00	#0.00		Not Observe	
		PAD, RR BUMPER, RH & LH ,	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	-X
	52462470 30	PAD, RR BUMPER, RH & LH,	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	X
	30	REINFORCEMENT					·		X
	13 52023470	REAR BUMPER	0.00	\$360.10	0.00	\$0.00	Replace	Not Given	
	52159479	COVER, RR BUMPER ASSY	1.00	\$478.90	100.00	\$0.00	Replace	Repair	R
	90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$707.10	0.00	\$0.00	Replace	Not Given	X
	F0007470	END DANIEL CUD ACCV	0.00	\$707.40	0.00	\$0.00		Not Cirra	
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	-X
		STRIDES LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
	10	UNDER CENTER					· ·		X
	30 66259470	UNDER , LH COVER, REAR FLOOR	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	
	58399470	COVER, REAR FLOOR	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	ΙX
	58398470 50	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	1X
	10	BUMPER, LH	0.00	£100.00	0.00	¢0.00	Donissa	Not Cirror	
		LENS & BODY ASSY, RR	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	-x
	81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
	51	COMBINATION LAMP , LH	0.00	Ø544.40	0.00	<b>CO 00</b>	Danlass	Not Civer	
		LENS & BODY, REAR	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	
	81551472	LENS & BODY, REAR COMBINATION LAMP, RH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
	00	LENG & BODY BEAD	0.00	0.400.00	0.00			N. 10:	
	89997301	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given	-X
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
	20	COVER, GUARD RR BUMPER LOWER	0.00	\$16.70	0.00	\$0.00	Replace	Not Given	X

Added Spare Parts / Material Usage After Surveyor Signed off									
Part	Portion	Stock	Part Name	Quantity	List Price \$	Discount	Final Price (\$)	ARC Check	Surveyor Check
Number		Number				(%)			
Total									

467.63 -20% 374.10

200.00 230.00

804.10

L/S \$800/-