



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS SINGAPORE CIVIL DEFENCE FORCE (MHA05) 91 UBI AVE 4 SINGAPORE 408827		Ref:	CS3/SCD24100406/Rqp3m4	
		Date:	05/11/2024	
		Code:	SCD	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	QX 2146Y	Veh. Inspected	GBF 7358S	
Policy No.	-	Coverage	0	
Claim No.	2024-123	Excess	\$0.00	
Assign From	SYABIL ISMAIL	Assign Date	23/10/2024	
2. Vehicle Details				
Make & Model	TOYOTA HIACE 3.0DX A	C.C	2982	
Engine No.	1KD2625424	Year of Reg.	24/02/2017	
Chassis No.	KDH2015022840	Colour	GREY	
Odometer	189874 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	FAIR	
Modification(s)	RIMS: NIL			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	195 R15C	MICHELIN	7	
L/H Front Tyre	195 R15C	MICHELIN	7	
R/H Rear Tyre	195 R15C	MICHELIN	7	
L/H Rear Tyre	195 R15C	MICHELIN	7	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
5. General Information				
Accident Date	18/10/2024	Inspection Date	28/10/2024 (17:04)	
Survey held at	TM MOTOR PTE LTD - 48 TOH GUAN ROAD EAST, TOH GUAN ENTERPRISE HUB #03-116 SINGAPORE 608586			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : GBF 7358S



PHOTOGRAPHS FOR VEHICLE NO. : GBF 7358S



PHOTOGRAPHS FOR VEHICLE NO. : GBF 7358S



PHOTOGRAPHS FOR VEHICLE NO. : GBF 7358S



PHOTOGRAPHS FOR VEHICLE NO. : GBF 7358S



PHOTOGRAPHS FOR VEHICLE NO. : GBF 7358S



PHOTOGRAPHS FOR VEHICLE NO. : GBF 7358S

