



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2501328

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:JOANNE YONG

INV Date 07/03/2025
Reference CD/FCI24100409/Uma3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLE 8975R
Insured Veh. SHA 1494B
Claim No. D24009361MFCT/CTPL/TPD2/JY
Policy No. D-24101861MFCT
Accident Date 22/10/2024
Inspection Date 29/10/2024

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref:	CD/FCI24100409/Uma3q2	
		Date:	07/03/2025	
		Code:	FCI2	
1. Policy Particulars :- DIRECT SETTLEMENT				
Insured Veh.	SHA 1494B	Veh. Inspected	SLE 8975R	
Policy No.	D-24101861MFCT	Coverage	0	
Claim No.	D24009361MFCT/CTPL/TPD2/JY	Excess	\$0.00	
Assign From	JOANNE YONG	Assign Date	23/10/2024	
2. Vehicle Details				
Make & Model	HONDA VEZEL 1.5X A	C.C	1496	
Engine No.	L15B4032448	Year of Reg.	04/08/2016	
Chassis No.	RU11112442	Colour	BLUE	
Odometer	108007 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	215/60R16	PIRELLI	6	
L/H Front Tyre	215/60R16	PIRELLI	6	
R/H Rear Tyre	215/60R16	PIRELLI	6	
L/H Rear Tyre	215/60R16	PIRELLI	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/10/2024	Inspection Date	29/10/2024	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLE 8975R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RH HEADLAMP	HOLDER CRACKED	\$2,150.00	\$2,150.00
1	FRT BUMPER	DENTED	\$895.00	\$895.00
1	FRT BUMPER RETAINER RH	CRACKED	\$38.00	\$38.00
10	FRT BUMPER CLIPS @\$5.50	NECESSARY	\$55.00	\$55.00
1	FRT BUMPER LOWER SPOILER	GRAZED	\$295.00	\$295.00
1	FRT RH FENDER	DENTED	\$425.00	\$425.00
1	FRT RH FENDER INNER COWLING	TORN	\$215.00	\$215.00
10	INNER COWLING CLIPS @\$5.50	MISSING	\$55.00	\$55.00
1	FRT RH FENDER PROTECTOR	MISSING / TORN	\$235.00	\$235.00
6	FRT RH FENDER PROTECTOR CLIPS @\$6.90	NOT NECESSARY	\$41.40	\$0.00
1	RH SIDE SKIRTS	NOT NECESSARY	\$355.00	\$0.00
12	RH SIDE SKIRTS CLIPS @\$5.50	NOT NECESSARY	\$66.00	\$0.00
1	FRT BUMPER REINFORCEMENT	NOT NECESSARY	\$425.00	\$0.00
1	FRT BUMPER BEAM RH (BELOW HEADLAMP)	NOT NECESSARY	\$75.00	\$0.00
	LESS 20.00% DISCOUNT		(\$1,065.08)	(\$872.60)
			\$4,260.32	\$3,490.40
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REPAIR FRT RH SPORT RIM (SN)	TO REPAIR SEE LABOUR	\$150.00	\$0.00
			\$150.00	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	WIRE CHECKING		\$30.00	\$20.00
	4 WHEEL ALIGNMENT		\$80.00	\$60.00
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF REPAIR FRT RH SPORT RIM.		\$600.00	\$400.00
	SPRAY PAINTING		\$700.00	\$600.00
			\$1,410.00	\$1,080.00
GRAND TOTAL			\$5,820.32	\$4,570.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$3,650.00
Report Ref No: CD/FCI24100409/Uma3q2			

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R



PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R



PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R





PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R





PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R



PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R




PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R



PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R



PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R



PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R



PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 12 of 12)

PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R



PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SLE 8975R

