

A-Tec Automotive Pte Ltd
8 Kaki Bukit Ave 4
#04-20 Premier
Singapore 415875

Not Authorized

4 Nov 2024

GBL 6569 A NISSAN NV350

new means 1/11/24 4 days. d/s \$ 3650 take photo. After rep. net item

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear windscreen moulding <i>NS</i>	\$ 105.00 <i>X</i>
2	1	Rear tailgate <i>Badly D.</i>	\$ 2,101.80 <i>✓</i>
3	2	Rear tailgate dampers <i>11</i>	\$ 390.00 <i>X</i>
4	1	Rear tailgate inner board <i>n1</i>	\$ 285.20 <i>X</i>
5	1	Rear tailgate lock cover <i>See</i>	\$ 45.00 <i>X</i>
6	1	Rear tailgate inner lock <i>Day X</i>	\$ 183.90 <i>✓</i>
7	1	Rear tailgate lock motor <i>n1</i>	\$ 125.80 <i>X</i>
8	1	Rear tailgate logo <i>new</i>	\$ 62.50 <i>✓</i>
9	1	Rear tailgate outer chrome garnish <i>11</i>	\$ 370.90 <i>X</i>
10	1	Rear tailgate rubber <i>See</i>	\$ 139.30 <i>X</i>
11	2	Rear tailgate side stoppers <i>11</i>	\$ 97.20 <i>X</i>
12	1	Rear tailgate "URVAN" emblem <i>new</i>	\$ 75.00 <i>✓</i>
13	2	Rear taillamps <i>11</i>	\$ 977.60 <i>X</i>
14	1	Rear end panel <i>n</i>	\$ 966.80 <i>X</i>
15	1	Rear step panel <i>See/Tor</i>	\$ 192.60 <i>✓</i>
16	1	Rear bumper <i>De/Tor</i>	\$ 899.80 <i>✓</i>
17	1	Rear bumper inner sponge <i>NS</i>	\$ 88.90 <i>X</i>
18	2	Rear bumper side holders <i>11</i>	\$ 97.00 <i>X</i>
19	1	Rear floor panel <i>11</i>	\$ 1,486.40 <i>X</i>
20	1	Rear floor panel top moulding <i>11</i>	\$ 145.00 <i>X</i>
			\$ 8,835.70
			less 10%
			\$ 883.57
			\$ 7,952.13

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	1	Rear windscreen sealant <i>new</i>	\$ 80.00 <i>40</i>
2	1	Rear tailgate "70KM/H" sticker <i>new</i>	\$ 28.00 <i>10</i>
3	1	Rear company sticker set <i>new</i>	\$ 280.00 <i>50</i>
4	1	Rear number plate <i>See</i>	\$ 50.00 <i>X</i>
5	1	Rear reverse sensor (1 set) <i>See</i>	\$ 280.00 <i>X</i>
6	1	Rear bumper clip (1 set) <i>new</i>	\$ 50.00 <i>30</i>
			\$ 768.00

Total parts : \$ 8,720.13

No	Description	Labour Charges
1	To remove, refit, replaced damaged lamps and check up rear electrical wiring	\$ 80.00 20
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 11 150.00 X
3	To remove and refit rear reverse sensor.	\$ 120.00 30
4	To transfer rear tailgate mechanism and wiring assembly to assist repair.	\$ 120.00 50
5	To remove and refit rear windscreen glass.	\$ 180.00 100
6	To apply undercoating on repaired and replaced panel.	\$ 200.00 30
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,600.00 500
8	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,500.00 600
Total labour :		\$ 3,950.00
Total parts :		\$ 8,720.13
Total labour :		\$ 3,950.00
Total repair cost :		\$ 12,670.13

LKM Auto Consultants licence notify
the Repairer of the following:

- To rectify defects/re-spray painting
- To display damaged parts, for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-confirmed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-3336-Y
102
3002.76
230
1330
486276