

ASS. REC. BY:

REF:

INC / CS/INC24100412/Kvh3

6

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: GZ 2239X

Policy No.

Claims No. MT/1300423-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/11 21 hrs @ Good Cabin

(red 27,634.21, 75%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 24-10-2024
VEHICLE : SNN7758L
MAKE/MODEL : TOYOTA / VOXY
CHASSIS NO : ZWR90-0121943
MILLAGE : 69416 KM
TYRE SIZE : 205/55/R17
DOA : 19-10-2024
TP INSURANCE : INCOME

Not Authorized
L1 By \$9000p
Resurvey After Painting
6 days

List items

01 PC	TAILGATE	1989.40	RM \$	2,352.40	✓
01 PC	TAILGATE EMBLEM (HYBRID)	64.90	RM \$	109.75	✓
01 PC	TAILGATE EMBLEM (LOGO)	91.80	RM \$	128.15	✓
01 PC	TAILGATE EMBLEM GARNISH		RM \$	756.80	✓
01 PC	TAILGATE OUTER LAMP LH	690.40	RM \$	1,162.52	✓
01 PC	TAILGATE OUTER LAMP RH		RM \$	1,162.52	X
02 PC	TAILGATE NUMBER PLATE LAMP @ \$169.36		\$	338.72	X
01 PC	TAILGATE OUTER HANDLE		\$	359.20	X
01 PC	REAR FENDER INNER TRIM BOARD LH		\$	1,080.48	X
01 PC	REAR FENDER INNER TRIM BOARD RH		\$	1,080.48	X
01 PC	TAILGATE CATCH LOCK		\$	85.30	X
01 PC	TAILGATE INNER LOCK	515.70	\$	679.28	✓
01 PC	TAILGATE INNER HANDLE		\$	67.20	X
01 PC	TAILGATE INNER TRIM BOARD		\$	770.48	✓
01 PC	TAILGATE WEATHERSTRIP		\$	314.58	✓
01 PC	TAILGATE POWER SENSOR LH		\$	670.16	X
01 PC	TAILGATE POWER SENSOR RH		\$	670.16	X
01 PC	TAILGATE POWER ABSORBER LH	1086.60	\$	1,426.96	✓
01 PC	TAILGATE POWER ABSORBER RH		\$	1,426.96	✓
01 PC	TAIL LAMP LH	881.45	RM \$	1,335.76	✓
01 PC	TAIL LAMP RH		\$	1,335.76	X
01 PC	REVERSE CAMERA		\$	1,554.60	X
01 PC	REAR CORNER PANEL LH		\$	206.30	X
01 PC	REAR CORNER PANEL RH		\$	206.30	X
01 PC	REAR CORNER PANEL RETAINER LH		\$	128.84	X
01 PC	REAR CORNER PANEL RETAINER RH		\$	128.84	X
01 PC	REAR BUMPER	1086	RM \$	2,525.64	✓
01 PC	REAR REFLECTOR LH		\$	140.25	X
01 PC	REAR REFLECTOR COVER LH		\$	120.80	X
01 PC	REAR REFLECTOR RH		\$	140.25	X
01 PC	REAR REFLECTOR COVER RH		\$	120.80	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

01 PC	REAR BUMPER RETAINER LH	\$ 120.29 X
01 PC	REAR BUMPER RETAINER RH	\$ 120.29 X
01 PC	REAR END PANEL	\$ 695.25 2
01 PC	REAR END PANEL TOP GARNISH 298.10	\$ 544.60 2
01 PC	REAR SPARE TYRE PANEL	\$ 900.40 X
01 PC	REAR SPARE TYRE PANEL BOARD	\$ 978.12 X
01 PC	REAR BUZZER	\$ 321.10 X
01 PC	REAR KEY ANTENNA SENSOR	\$ 102.60 2
01 PC	REAR WINDSCREEN	Shorter \$ 950.80 ✓
01 PC	REAR WINDSCREEN MOULDING	nn \$ 258.30 X
01 PC	REAR WIPER MOTOR	\$ 853.40 X
01 PC	REAR WIPER ARM	\$ 212.30 X
01 PC	REAR WIPER BLADE	\$ 85.10 X
01 PC	REAR WIPER NOZZLE	\$ 56.70 X
01 PC	COMPUTER , MULTIPLEX NETWORK DOOR 1098.72 ✓ 728.40	\$ 28,785.49

Special Nett Item:

01 PC	PRIVATE HIRE STICKER	\$ 25.00 ✓
04 PC	PARKING SENSOR @ \$380	\$ 1,520.00 X
01 PC	REAR DASH CAMERA ✓	MIT \$ 750.00 450.00
01 PC	WINDSCREEN SEALANT	MC \$ 100.00
01 PC	NUMBER PLATE	\$ 30.00 } 45.00
01 PC	NUMBER PLATE COVER	\$ 25.00 }
01 PC	PANEL SEALANT	300.00 2
		\$ 2,550.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$ 1,500.00 600
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$ 1,400.00 700
3. TO SUPPLY LABOUR TO REMOVE & REFIT UP HOSTLER FOR REPAIR	\$ 300.00 600
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$ 300.00 200
5. TO SUPPLY DIAGNOTIC & REPROGRAMMING	\$ 400.00 X
6. TO SUPPLY LABOUR TO REMOVE & REFIT WINDSCREEN (REAR)	\$ 300.00 1200
	\$ 4,200.00

TOTAL PARTS

\$ 28,785.49

SPECIAL NETT ITEM

\$ 2,550.00

TOTAL LABOUR

\$ 4,200.00

TOTAL COST OF REPAIR

\$ 35,535.49