

ASS. REC. BY:

REF: INC 1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$190k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 5-6 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNV 775PL

Yr Regn: 12, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vaux

c.c 1797

Colour: M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading: 89416

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR 90

0121943

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mm

R/Bal. 2 mm

L/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 19/10/24

D.O.A. 24/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

S - RS. SI

Fees

Others

Add Fee: _____

: Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 24-10-2024
VEHICLE : SNN7758L
MAKE/MODEL : TOYOTA / VOXY
CHASSIS NO : ZWR90-0121943
MILLAGE : 69416 KM
TYRE SIZE : 205/55/R17
DOA : 19-10-2024
TP INSURANCE : INCOME

Not Authorised

L1 By B

Running After Rain

5-6 days

List items

01 PC	TAILGATE	\$ 2,352.40	✓
01 PC	TAILGATE EMBLEM (HYBRID)	\$ 109.75	✓
01 PC	TAILGATE EMBLEM (LOGO)	\$ 128.15	✓
01 PC	TAILGATE EMBLEM GARNISH	\$ 756.80	?
01 PC	TAILGATE OUTER LAMP LH	\$ 1,162.52	✓
01 PC	TAILGATE OUTER LAMP RH	\$ 1,162.52	X
02 PC	TAILGATE NUMBER PLATE LAMP @ \$169.36	\$ 338.72	?
01 PC	TAILGATE OUTER HANDLE	\$ 359.20	X
01 PC	REAR FENDER INNER TRIM BOARD LH	\$ 1,080.48	X
01 PC	REAR FENDER INNER TRIM BOARD RH	\$ 1,080.48	✓
01 PC	TAILGATE CATCH LOCK	\$ 85.30	X
01 PC	TAILGATE INNER LOCK	\$ 679.28	?
01 PC	TAILGATE INNER HANDLE	\$ 67.20	X
01 PC	TAILGATE INNER TRIM BOARD	\$ 770.48	✓
01 PC	TAILGATE WEATHERSTRIP	\$ 314.58	?
01 PC	TAILGATE POWER SENSOR LH	\$ 670.16	?
01 PC	TAILGATE POWER SENSOR RH	\$ 670.16	?
01 PC	TAILGATE POWER ABSORBER LH	\$ 1,426.96	?
01 PC	TAILGATE POWER ABSORBER RH	\$ 1,426.96	?
01 PC	TAIL LAMP LH	\$ 1,335.76	✓
01 PC	TAIL LAMP RH	\$ 1,335.76	X
01 PC	REVERSE CAMERA	\$ 1,554.60	X
01 PC	REAR CORNER PANEL LH	\$ 206.30	X
01 PC	REAR CORNER PANEL RH	\$ 206.30	X
01 PC	REAR CORNER PANEL RETAINER LH	\$ 128.84	✓
01 PC	REAR CORNER PANEL RETAINER RH	\$ 128.84	X
01 PC	REAR BUMPER	\$ 2,525.64	✓
01 PC	REAR REFLECTOR LH	\$ 140.25	X
01 PC	REAR REFLECTOR COVER LH	\$ 120.80	X
01 PC	REAR REFLECTOR RH	\$ 140.25	X
01 PC	REAR REFLECTOR COVER RH	\$ 120.80	X

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

01 PC	REAR BUMPER RETAINER LH
01 PC	REAR BUMPER RETAINER RH
01 PC	REAR END PANEL
01 PC	REAR END PANEL TOP GARNISH
01 PC	REAR SPARE TYRE PANEL
01 PC	REAR SPARE TYRE PANEL BOARD
01 PC	REAR BUZZER
01 PC	REAR KEY ANTENNA SENSOR
01 PC	REAR WINDSCREEN
01 PC	REAR WINDSCREEN MOULDING
01 PC	REAR WIPER MOTOR
01 PC	REAR WIPER ARM
01 PC	REAR WIPER BLADE
01 PC	REAR WIPER NOZZLE

\$	120.29	X
\$	120.29	X
\$	695.25	?
\$	544.60	?
\$	900.40	X
\$	978.12	X
\$	321.10	?
\$	102.60	?
Shorter \$	950.80	✓
na \$	258.30	X
\$	853.40	X
\$	212.30	X
\$	85.10	X
\$	56.70	X
\$	<u>28,785.49</u>	

Special Nett Item:

01 PC	PRIVATE HIRE STICKER
04 PC	PARKING SENSOR @ \$380
01 PC	REAR DASH CAMERA
01 PC	WINDSCREEN SEALANT
01 PC	NUMBER PLATE
01 PC	NUMBER PLATE COVER
01 PC	PANEL SEALANT

\$	25.00	✓
\$	1,520.00	?
\$	750.00	X
me \$	100.00	
\$	30.00	45m
\$	25.00	
\$	100.00	?
\$	<u>2,550.00</u>	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO REMOVE & REFIT UP HOSTLER FOR REPAIR
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY DIAGNOTIC & REPROGRAMMING
6. TO SUPPLY LABOUR TO REMOVE & REFIT WINDSCREEN (REAR)

\$	1,500.00	?
\$	1,400.00	Food
\$	300.00	601
\$	300.00	201
\$	400.00	?
\$	300.00	1201
\$	<u>4,200.00</u>	

TOTAL PARTS

\$ 28,785.49

SPECIAL NETT ITEM

\$ 2,550.00

TOTAL LABOUR

\$ 4,200.00

TOTAL COST OF REPAIR

\$ 35,535.49