



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 24-10-2024
VEHICLE : SNN7758L
MAKE/MODEL : TOYOTA / VOXY
CHASSIS NO : ZWR90-0121943
MILLAGE : 69416 KM
TYRE SIZE : 205/55/R17
DOA : 19-10-2024
TP INSURANCE : INCOME

Not Authorized
L1 By \$9000p
Resurvey After Rain
6 days

List items

01 PC	TAILGATE	1989.40	By \$	2,352.40	✓
01 PC	TAILGATE EMBLEM (HYBRID)	64.90	Re \$	109.75	✓
01 PC	TAILGATE EMBLEM (LOGO)	91.80	Re \$	128.15	✓
01 PC	TAILGATE EMBLEM GARNISH		my CBT	756.80	✓
01 PC	TAILGATE OUTER LAMP LH	690.40	CM TAILGATE	1,162.52	✓
01 PC	TAILGATE OUTER LAMP RH		Re \$	1,162.52	X
02 PC	TAILGATE NUMBER PLATE LAMP @ \$169.36		\$ Re	338.72	X
01 PC	TAILGATE OUTER HANDLE		\$ Re	359.20	X
01 PC	REAR FENDER INNER TRIM BOARD LH		\$ Re	1,080.48	X
01 PC	REAR FENDER INNER TRIM BOARD RH		\$ Re	1,080.48	X
01 PC	TAILGATE CATCH LOCK		\$ Re	85.30	X
01 PC	TAILGATE INNER LOCK	515.70	\$ Re	679.28	✓
01 PC	TAILGATE INNER HANDLE		\$ Re	67.20	X
01 PC	TAILGATE INNER TRIM BOARD		Re	770.48	✓
01 PC	TAILGATE WEATHERSTRIP		ADIT	314.58	✓
01 PC	TAILGATE POWER SENSOR LH		\$ Re	670.16	X
01 PC	TAILGATE POWER SENSOR RH		\$ Re	670.16	X
01 PC	TAILGATE POWER ABSORBER LH	1086.60	\$ Re	1,426.96	✓
01 PC	TAILGATE POWER ABSORBER RH		\$ Re	1,426.96	✓
01 PC	TAIL LAMP LH	881.45	CM	1,335.76	✓
01 PC	TAIL LAMP RH		\$ Re	1,335.76	X
01 PC	REVERSE CAMERA		\$ Re	1,554.60	X
01 PC	REAR CORNER PANEL LH		\$ Re	206.30	X
01 PC	REAR CORNER PANEL RH		\$ Re	206.30	X
01 PC	REAR CORNER PANEL RETAINER LH		\$ Re	128.84	X
01 PC	REAR CORNER PANEL RETAINER RH		\$ Re	128.84	X
01 PC	REAR BUMPER	1086	Re	2,525.64	✓
01 PC	REAR REFLECTOR LH		\$ Re	140.25	X
01 PC	REAR REFLECTOR COVER LH		\$ Re	120.80	X
01 PC	REAR REFLECTOR RH		\$ Re	140.25	X
01 PC	REAR REFLECTOR COVER RH		\$ Re	120.80	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

01 PC	REAR BUMPER RETAINER LH	\$ 120.29	X
01 PC	REAR BUMPER RETAINER RH	\$ 120.29	X
01 PC	REAR END PANEL	\$ 695.25	2
01 PC	REAR END PANEL TOP GARNISH	\$ 544.60	2
01 PC	REAR SPARE TYRE PANEL	\$ 900.40	X
01 PC	REAR SPARE TYRE PANEL BOARD	\$ 978.12	X
01 PC	REAR BUZZER	\$ 321.10	X
01 PC	REAR KEY ANTENNA SENSOR	\$ 102.60	2
01 PC	REAR WINDSCREEN	\$ 950.80	✓
01 PC	REAR WINDSCREEN MOULDING	\$ 258.30	X
01 PC	REAR WIPER MOTOR	\$ 853.40	X
01 PC	REAR WIPER ARM	\$ 212.30	X
01 PC	REAR WIPER BLADE	\$ 85.10	X
01 PC	REAR WIPER NOZZLE	\$ 56.70	X
01 PC	COMPUTER , MULTIPLEX NETWORK DOOR	\$ 1098.72	✓
		\$ 28,785.49	

Special Nett Item:

01 PC	PRIVATE HIRE STICKER	\$ 25.00	✓
04 PC	PARKING SENSOR @ \$380	\$ 1,520.00	X
01 PC	REAR DASH CAMERA	\$ 750.00	450.00
01 PC	WINDSCREEN SEALANT	\$ 100.00	
01 PC	NUMBER PLATE	\$ 30.00	45.00
01 PC	NUMBER PLATE COVER	\$ 25.00	
01 PC	PANEL SEALANT	\$ 100.00	2
		\$ 2,550.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$ 1,500.00	600
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$ 1,400.00	700
3. TO SUPPLY LABOUR TO REMOVE & REFIT UP HOSTLER FOR REPAIR	\$ 300.00	601
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$ 300.00	201
5. TO SUPPLY DIAGNOTIC & REPROGRAMMING	\$ 400.00	X
6. TO SUPPLY LABOUR TO REMOVE & REFIT WINDSCREEN (REAR)	\$ 300.00	1201
	\$ 4,200.00	

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

\$ 28,785.49
\$ 2,550.00
\$ 4,200.00
<u>\$ 35,535.49</u>