

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24100418/EVP3E2**Date:** 06/11/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MAA00308
Claimant Vehicle No :	SHA7870J	Insured Vehicle No :	SNK3800P
Date of Loss:	22/10/2024	Nature of Claim:	TP
		Claim No:	M2406184

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7870J		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 HATCHBACK(AT) (2WD) (A)	Engine No:	2ZR2X22678
Reg. Date:	31/10/2023 (Man. Year: 2023)	Chassis No:	JTDAE3AU603001810
Colour:	Blue	Odometer:	96102 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/60 R17	Rear Tyre Size:	195/60 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,561.24	1,085.96	2,475.28	69.51
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	2,380.00	1,340.00	1,040.00	43.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,953.24	2,437.96	3,515.28	59.05
+ GST 9.00/9.00% (\$\$)	535.79	219.42	316.37	59.05
Nett Amount (\$\$)	6,489.03	2,657.38	3,831.65	59.05

INSPECTION

Date of Assignment:	24/10/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	24/10/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Nov 2024)
Parts:	144	TOYOTA PRIUS TAXI 1.8 HATCHBACK(AT)(2WD) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7870J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	124.28 FL	*124.28 FL
2	1		*REAR TRUNK LID LOGO (HEV)	Necessary	62.14 FL	*62.14 FL
3	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Not Necessary	81.43 FL	*- FL
4	1		*REAR TRUNK LID COVER	Repair	2,280.10 FL	*- FL
5	1		*REAR BUMPER	Dented	595.10 FL	*595.10 FL
6	1		*REAR BUMPER LOWER COVER	Cut	511.10 FL	*511.10 FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	451.50 FL	*- FL
8	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
9	1		*REAR UTRASONIC SENSOR	Not Necessary	466.00 FL	*- FL
10	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 FS	*40.00 FS
11	1		*REAR TRUNK LID COMFORT & TEL NO. STICKER	Necessary	30.00 FS	*60.00 FS
12	2		*WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,709.65	1,414.62
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,148.41	328.66
Total Parts (\$\$)	3,561.24	1,085.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (S\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Panel Beating (REFER TO SUPPLEMENTARY)	New	140.00	0.00
2	Spray Painting Charge	New	800.00	560.00
3	Check Lighting & Wiring Charge	New	60.00	0.00
4	Remove/Refix Rear Windscreen Upper & Lower	New	180.00	0.00
5	Remove/Refix Reverse Sensor	New	60.00	20.00
Supplementary #1				
Labour Items				
6	PANEL BEATING	New	1,140.00	760.00
Gross Labour Cost (S\$)			2,380.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >