



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2500999

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:CHRIS LIM

INV Date 18/02/2025
Reference CD/FCI24100420/Rpa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 1660D
Insured Veh. SHD 7151K
Claim No. D24009287MFCT/2
Policy No. D-24101861MFCT
Accident Date 21/10/2024
Inspection Date 28/10/2024

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (9%)	45.00
Grand Total	545.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN:CHRIS LIM			Ref: CD/FCI24100420/Rpa3q2(N) Date: 18/02/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 7151K	Veh. Inspected	SMA 1660D
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24009287MFCT/2	Excess (\$)	0.00
	Assign From	CHRIS LIM	Assign Date	28/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI ECLIPSE CROSS 1.5	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JMAXTGK1WJZ001687	Colour	RED
	Odometer	75422 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R18	YOKOHAMA	6 mm
	L/H Front Tyre	225/55 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	225/55 R18	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/10/2024	Inspection Date	28/10/2024
	Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 1660D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	80.00	20.00
1	CNC BADGE (SN)	NECESSARY	50.00	50.00
1	NUMBER PLATE (SN)	NOT NECESSARY	100.00	-
1	FACE ,RR BUMPER (SN)	DEFORMED	548.00	548.00
1	EXTENSION RR BUMPER (SN)	DEFORMED	150.00	150.00
1	CORE RR BUMPER (SN)	DEFORMED	41.00	41.00
1	CORE RR BUMPER (SN)	SERVICEABLE	35.00	-
1	REINFORCEMENT RR BUMPER (SN)	BENT	525.00	525.00
1	BRKT R/BMPR FACE SIDE LH (SN)	SERVICEABLE	26.00	-
1	BRKT R/BMPR FACE SIDE RH (SN)	SERVICEABLE	26.00	-
1	COVER RR BUMPER LH (SN)	SERVICEABLE	170.00	-
1	COVER RR BUMPER LH (SN)	SERVICEABLE	170.00	-
1	PANEL ASSY TAILGATE (SN)	BENT	1,125.00	1,125.00
1	GARNISH TAILGATE (SN)	NOT NECESSARY	518.00	-
1	DAM TAILGATE LWR (SN)	NOT NECESSARY	14.00	-
1	GLASS TAILGATE WINDOW (SN)	NECESSARY	670.00	670.00
2	SPACER TAILGATE (SN)	NECESSARY	18.00	18.00
2	SPACER TAILGATE (SN)	NECESSARY	18.00	18.00
3	CLIP TAILGATE (SN)	NOT NECESSARY	12.00	-
1	PIN TAILGATE WINDOW (SN)	NOT NECESSARY	6.00	-
4	SPACER QTR WINDOW (SN)	NECESSARY	32.00	32.00
8	FASTENER ,WINDSHIELD (SN)	NECESSARY	64.00	64.00
2	STOPPER WINDSHIELD GLASS (SN)	NECESSARY	8.00	8.00
1	MARK THREE DIA (SN)	NECESSARY	61.00	61.00
1	MARK ECLIPSE CROSS (SN)	NECESSARY	92.00	92.00
1	MARK MITSUBISHI (SN)	NOT NECESSARY	81.00	-
1	DAM TAILGATE LWR (SN) (ADDITIONAL)	NECESSARY	14.00	14.00
1	PIN TAILGATE WINDOW (SN) (ADDITIONAL)	NECESSARY	6.00	6.00
2	CLIP TAILGATE (SN) (ADDITIONAL)	NECESSARY	8.00	8.00
1	PANEL RR END (SN) (ADDITIONAL)	BENT	503.00	503.00
1	MUFFLER EXHAUST MAIN (SN) (ADDITIONAL)	BENT	545.00	545.00

Report Ref No. CD/FCI24100420/Rpa3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ANT ,KEYLESS OPERATION RR (SN) (ADDITIONAL)	CRACKED	102.00	102.00
1	BUZZER ,KEYLESS OPERATION RR (SN) (ADDITIONAL)	CRACKED	96.00	96.00
1	COVER RR BUMPER LH (SN) (ADDITIONAL)	CRACKED	170.00	170.00
1	COVER RR BUMPER RH (SN) (ADDITIONAL)	CRACKED	170.00	170.00
8	CLIP BUMPER (SN) (ADDITIONAL)	NECESSARY	16.00	16.00
10	CLIPS (SN) (ADDITIONAL)	NECESSARY	20.00	20.00
			6,290.00	5,072.00
	LABOUR			
	RENEW RR BUMPER SKID PLATE TAILGATE REPAIR END PANEL AND RENEW DAMAGED PARTS.		3,200.00	1,280.00
	SPRAY RR BUMPER TAILGATE END PANEL.		1,650.00	1,100.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRICAL CONTROL SYSTEM.		280.00	280.00
	CHECK WIRING AND ELECTRICAL.		150.00	50.00
	CALIBRATION ON THE REAR AUTO TAILGATING SENSOR .	NOT NECESSARY	280.00	-
	REMOVE AND REFIT /TRANSFER REAR TAILGATE MECHANISM TRIM .		280.00	160.00
	REMOVE AND REFIT SENSOR .		100.00	80.00
	RUST PROOFING.		200.00	80.00
	APPLY SEALANT ON AFFECTED AREA.		150.00	80.00
	RENEW RR GLASS .		380.00	380.00
	SEALING WINDSCREEN.		180.00	100.00
	WATER LEAK TEST.		50.00	50.00
	SUPPLY SOLAR FILM TINT.		280.00	280.00
	REPAIR RENEW RR END PANEL. (ADDITIONAL)		1,920.00	1,920.00
	PAINTWORK REAR END PANEL. (ADDITIONAL)		550.00	550.00
	REPAIR REPLACE REAR EXHAUST MUFFLER . (ADDITIONAL)		320.00	320.00
			9,970.00	6,710.00
GRAND TOTAL			16,260.00	11,782.00

Report Ref No. CD/FCI24100420/Rpa3q2(N)



RECOMMENDED COST OF REPAIRS			11,782.00
-----------------------------	--	--	-----------

Report Ref No. CD/FCI24100420/Rpa3q2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 1660D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 1660D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

