



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Tan Ban Leng (chen Wanlong) 42 Tai Keng Gardens Singapore 535323 Contact No Mobile: 98766288	Cust No/Name	/Tan Ban Leng (Chen Wanlong)
	Reg No/Reg Date	SMA1660D / 30/05/2018
	Date In/Mileage	/ 0
	Chassis No	JMAXTGK1WJZ001687
	Engine No	4B40DL5651
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C 2WD (T12)
	Colour/Trim	P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00147	Cash	23/10/2024/ 15:09		1015/ Vikneswaran Naidu A	51042		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER, SKID PLATE, TAILGATE, REPAIR END PANEL AND RENEW DAMAGED PARTS							3200.00
E PNT98000 SPRAY RR BUMPER, TAILGATE, END PANEL							1650.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							280.00
A 10028901 CHECK WIRING AND ELECTRICAL							150.00
A 10028901 CALIBRATION ON THE REAR AUTO TAILGATING SENSOR							280.00
E PNT88000 REMOVE AND REFIT/TRASNFER REAR TAILAGTE MECHANISM TRIM							280.00
E PNT88000 REMOVE AND REFIT SENSOR							100.00
M SUNDRY SUPPLY NUMBER PLATE							100.00
M SUNDRY RUST PROOFING							200.00
M SUNDRY APPLY SEALANT ON AFFECTED AREA							150.00
M SUNDRY SUPPLY CNC BADGE							50.00
M SUNDRY SUNDRIES							80.00
E PNT88000 RENEW RR GLASS							380.00
M SUNDRY SEALING WINDSCREEN							180.00
M SUNDRY WATER LEAK TEST							50.00
M SUNDRY SUPPLY SOLAR FILM TINT							280.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Tan Ban Leng (chen Wanlong) 42 Tai Keng Gardens Singapore 535323 Contact No Mobile: 98766288	Cust No/Name	/Tan Ban Leng (Chen Wanlong)
	Reg No/Reg Date	SMA1660D / 30/05/2018
	Date In/Mileage	/ 0
	Chassis No	JMAXTGK1WJZ001687
	Engine No	4B40DL5651
	Make/Model	MIT/ECLIPSE CROSS 1.5 T/C 2WD (T12)
	Colour/Trim	P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00147	Cash	23/10/2024/ 15:09		1015/ Vikneswaran Naidu A	51042
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M FACE,RR BUMPER		1.00	548.00	00.00	548.00
M EXTENSION,RR BUMPER		1.00	150.00	00.00	150.00
M CORE,RR BUMPER		1.00	41.00	00.00	41.00
M CORE,RR BUMPER		1.00	35.00	00.00	35.00
M REINFORCEMENT,RR BUMPER		1.00	525.00	00.00	525.00
M BRKT,R/BMPR FACE SIDE,LH		1.00	26.00	00.00	26.00
M BRKT,R/BMPR FACE SIDE,RH		1.00	26.00	00.00	26.00
M COVER,RR BUMPER,LH		1.00	170.00	00.00	170.00
M COVER,RR BUMPER,LH		1.00	170.00	00.00	170.00
M PANEL ASSY,TAILGATE		1.00	1125.00	00.00	1125.00
M GARNISH,TAILGATE		1.00	518.00	00.00	518.00
M DAM,TAILGATE,LWR		1.00	14.00	00.00	14.00
M GLASS,TAILGATE WINDOW		1.00	670.00	00.00	670.00
M SPACER,TAILGATE		2.00	9.00	00.00	18.00
M SPACER,TAILGATE		2.00	9.00	00.00	18.00
M CLIP,TAILGATE		3.00	4.00	00.00	12.00
M PIN,TAILGATE WINDOW		1.00	6.00	00.00	6.00
M SPACER,QTR WINDOW		4.00	8.00	00.00	32.00
M FASTENER,WINDSHIELD		8.00	8.00	00.00	64.00
M STOPPER,WINDSHIELD GLASS		2.00	4.00	00.00	8.00
M MARK,THREE-DIA		1.00	61.00	00.00	61.00
M MARK,ECLIPSE CROSS		1.00	92.00	00.00	92.00
M MARK,MITSUBISHI		1.00	81.00	00.00	81.00

Confirm & accepted by

Nett 11,820.00
 9% GST on 11820.00 1063.80
 Total Payable 12,883.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.