

ASSIGNMENT

From: _____ Date: _____
 Estin: _____
 OD / TP RES / TP RES / OD RES / EVA / INV / MV
 To in Vehicle NO: _____
 at W/O _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)

Veh No: SGX8737X Yr Regn: 2007, Sept
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Vios C.D. 1497
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 178206 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRO53HY9305013498
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 205/45R16
 R: 205/45R16

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rport Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>22/10/24</u>

*Survey held at JL Perfect
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Exp</u>
	<u>COE Expiry : 10/09/2027</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV : 29K</u>
	<u>PV : 12.8K</u>
	<u>Nett : 16.2K</u>
	<u>530E</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) Date/Time, File Return to?
 2) _____
 Report Format: _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invt (\$) : _____
 Survey Fee: _____
 Transportation: _____
 Photos _____
 Others _____

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 21.10.2024

TO : **ERGO** MOTOR CLAIMS DEPTS
VEHICLE NO : **SGX8737X**
MODEL : **TOYOTA VIOS**
DATE OF ACCIDENT : 19.10.2024
TIME OF ACCIDENT : 15:50 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehnd</i>	1	\$ 470.10	\$ 470.10
2	REAR BUMPER REFLECTOR <i>Contd</i>	2	\$ 74.60	\$ 149.20
3	REAR BUMPER SIDE RETAINER (FRONT) <i>2pc</i>	2	\$ 83.10	\$ 166.20
4	REAR BUMPER SIDE RETAINER (REAR) <i>1pc</i>	2	\$ 64.90	\$ 129.80
5	TAIL LAMP <i>Contd</i>	2	\$ 450.00	\$ 900.00
6	TAIL LAMP PANEL <i>2pc LH Buckled</i>	2	\$ 630.60	\$ 1,261.20
7	REAR FENDER INNER COWLING <i>2pc</i>	2	\$ 395.60	\$ 791.20
8	REAR FENDER INNER TRIM LH <i>1pc</i>	2	\$ 255.70	\$ 511.40
9	BOOT LID <i>Buckled</i>	1	\$ 575.00	\$ 575.00
10	BOOT LID LOGO <i>2pc</i>	1	\$ 65.00	\$ 65.00
11	BOOT LID EMBLEM 'VIOS' <i>1pc</i>	1	\$ 65.00	\$ 65.00
12	BOOT LID EMBLEM 'E' <i>1pc</i>	1	\$ 55.00	\$ 55.00
13	BOOT LID OUTER MOULDING <i>Not included</i>	1	\$ 158.10	\$ 158.10
14	BOOT LID NUMBER PLATE LAMP <i>1pc</i>	2	\$ 42.30	\$ 84.60
15	BOOT LID STOPPER <i>new</i>	2	\$ 19.00	\$ 38.00
16	BOOT LID TOP LOCK <i>2pc</i>	1	\$ 125.40	\$ 125.40
17	BOOT LID LOWER LOCK <i>new</i>	1	\$ 25.00	\$ 25.00
18	BOOT LID OUTER KEY LOCK <i>new</i>	1	\$ 225.00	\$ 225.00
19	BOOT LID WEATHER STRIP <i>1pc</i>	1	\$ 205.00	\$ 205.00
20	BOOT LID HINGE <i>new</i>	2	\$ 70.00	\$ 140.00
21	REAR END PANEL <i>Dented</i>	1	\$ 439.00	\$ 439.00
22	REAR END PANEL TOP GARNISH <i>Dehnd</i>	1	\$ 230.00	\$ 230.00
23	REAR FLOOR PANEL <i>Repair</i>	1	\$ 695.60	\$ 695.60
24	REAR FLOOR PANEL TOP BOARD <i>torn</i>	1	\$ 150.10	\$ 150.10
25	REAR FLOOR PANEL TOP SPONGE (SIDE) <i>Dented</i>	2	\$ 245.60	\$ 491.20
26	REAR FLOOR PANEL TOP SPONGE (SIDE) COVER BOARD <i>new</i>	2	\$ 41.20	\$ 82.40
27	REAR FLOOR PANEL TOP SPONGE (INNER) <i>new</i>	1	\$ 220.10	\$ 220.10
28	REAR FLOOR SIDE PANEL LH <i>Repair</i>	1	\$ 139.60	\$ 139.60

Handwritten notes and checkmarks on the right side of the table, including a circled total of 630.60 for item 6 and various '+' and '-' signs.

TO : **ERGO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGX8737X**
 MODEL : **TOYOTA VIOS**
 DATE OF ACCIDENT : 19.10.2024
 TIME OF ACCIDENT : 15:50 HOURS

29	REAR SPARE TYRE BOLT <i>Atc m</i>	1	\$ 48.00	\$ 48.00	+
30	REAR CHASSIS MEMBER RH <i>Atc m</i>	1	\$ 694.30	\$ 694.30	+

TOTAL PRICE \$ 9,330.50
 LESS 25% \$ 2,332.63
SUB TOTAL PRICE \$ 6,997.88

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Atc m</i>	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIPS (SET) <i>m</i>	1	\$ 80.00	\$ 80.00	30
3	REAR FENDER INNER COWLING CLIPS (SET) <i>Atc m</i>	1	\$ 80.00	\$ 80.00	+
4	REAR FENDER INNER TRIM CLIPS (SET) <i>Atc m</i>	1	\$ 80.00	\$ 80.00	+
5	TAIL LAMP CLIPS (SET) <i>Atc m</i>	1	\$ 30.00	\$ 30.00	+
6	TAIL LAMP PANEL SEALANT	2	\$ 60.00	\$ 120.00	+
7	REAR END PANEL INSULATION SEAL <i>m</i>	1	\$ 150.00	\$ 150.00	60
8	REAR FLOOR PANEL INSULATION SEAL <i>Atc m</i>	1	\$ 350.00	\$ 350.00	+
9	TRIANGLE BREAKDOWN SIGN <i>Delord</i>	1	\$ 180.00	\$ 180.00	60
10	REVERSE SENSOR <i>Delord</i>	1	\$ 220.00	\$ 220.00	20

TOTAL \$ 1,370.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, KNOCK, GRAZE, ADJUST, REPLACE NEW PARTS	\$ 1,800.00	800
2	TO PUTTY, SPRAY PAINT, POLISH, WAX ADJACENT PANELS	\$ 1,800.00	1000
3	TUFF COAT	\$ 250.00	60
4	WIRING/ BULB CHECKING	\$ 350.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	X
8	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 100.00	X
9	REMOVE AND REFIX REAR EXHAUST	\$ 180.00	X
10	TRANSFER BOOT LID MECHANISM	\$ 80.00	60

TO : **ERGO** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SGX8737X**
 MODEL : **TOYOTA VIOS**
 DATE OF ACCIDENT : 19.10.2024
 TIME OF ACCIDENT : 15:50 HOURS

11	TO CONDUCT WATER LEAKAGE TEST	\$ 80.00	P
12	REAR CHASSIS MEMBER ALIGHMENT	\$ 250.00	P
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 5,580.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,367.88
 TOTAL LABOUR COST : \$ 5,580.00
 TOTAL REPAIR COST : \$ 13,947.88

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

Adrian G
L/S 22/10/24
07 Days

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: