



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

1/58900

GST Reg No.: 200704951N

Co Reg No.: 200704951N

not Authorized

Date: 23/10/2024

India International Insurance Pte Ltd

Policy No.: D24MPC003636

64 Cecil Street

Vehicle No.: SJQ4541X

#04/06 IOB Building

Model: HYUNDAI AVANTE

Singapore 049711

D.O.A 21/10/2024

90096608

24/10/24

54255 \$600

Wheeler Atty

Estimate Repair Cost For SJQ4541X

6 days

1/58900

NO.	DESCRIPTIONS	AMOUNT
1	1 PC FRONT BUMPER	\$ 215 658.20 ✓
2	1 PC FRONT BUMPER TOP RUBBER SEAL	\$ AN 85.20 X
3	2 PCS FRONT BUMPER TOP BRACKET	\$ NS 197.20 X
4	2 PCS FRONT BUMPER RETAINER	\$ set 173.80 ✓
5	1 PC FRONT BUMPER SPONGE	\$ NF 225.60 X
6	1 PC FRONT BUMPER REINFORCEMENT	319.20 \$ set 589.50 ✓
7	1 PC FRONT BUMPER RADIATOR GRILLE	582.00 \$ cre 1,082.90 ✓
8	1 PC SUPPORT PANEL TOP GARNISH	\$ NS 202.50 X
9	1 PC FRONT SUPPORT PANEL	cro / \$ succ 987.50 ✓
10	2 PCS FRONT HEADLAMPS	\$ holder 3,512.80 ✓
11	1 PC FRONT BONNET	\$ succ 1,971.20 ✓
12	1 PC FRONT BONNET INSULATOR	241.20 \$ 241.20 385.90 ✓
13	1 PC RADIATOR	\$ 241.20 619.00 ✓
14	1 PC RADIATOR FAN MOTOR ASSY	\$ 241.20 596.00 ✓
15	1 PC RADIATOR TOP HOSE	\$ 7m 42.00 ✓
16	1 PC RADIATOR BOTTOM HOSE	\$ 1m 42.00 X
17	1 PC AIR CON CONDENSER	\$ set 991.00 ✓
18	1 PC AIR CON SUCTION PIPE	302.00 \$ set 643.00 ✓
19	1 PC AIR CON DISCHARGE PIPE	\$ SU 192.00 X
20	1 PC NUMBER PLATE	\$ 320 30.00 ✓
		\$ 13,227.30
	LESS 20%	\$ (2,645.46)
		\$ 10,581.84

MISC & LABOUR CHARGE

21	TOWING
22	REMOVE & REFIX FRONT UNDERCARRIAGE

\$ 200.00 60

\$ 400.00 X



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

NO.	DESCRIPTIONS	AMOUNT
23	REMOVE & REFIX FRONT PORTION, KNOCKING, WELDING, CUT & JACK	\$ 900 1,800.00
24	CHASSIS FRAME. ALIGNMENT	
25	RESPRAY FRONT PORTION. TOUCH-UP & POLISHING	\$ 900 1,500.00
	ELECTRICAL & FOCUS WIRING	\$ 20 50.00
26	COMPUTERIZE & 4 WHEELS ALIGNMENT	\$ 11 X 100.00
27	TO REMOVE & RFIX FRONT SUPPORT PANEL & HEADLAMP RH. ALIGNMENT	\$ refer main labour 400.00 X
28	REMOVE AIR CON & REFILL GAS	\$ 100.00 ✓
		<u>\$ 4,550.00</u>
	TOTAL:	<u>\$ 15,131.84</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, if necessary
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-11482-60
202
9186.08
1980
11166.08
202
8932



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

Date: 14/11/2024

India International Insurance Pte Ltd

Policy No.: D24MPC003636

6 Raffles Quay

Vehicle No.: SJQ4541X

#22-00

Model: HYUNDAI AVANTE

Singapore 048580

D.O.A 21/10/2024

Estimate Repair Cost For SJQ4541X

Supplementary

NO.	DESCRIPTIONS	AMOUNT
1	1 pc bonnet lock <i>Beat/tw1</i>	\$ 97.00 ✓
2	2 pcs bonnet hinges <i>beat</i>	\$ 170.00 ✓
3	1 pc horn unit <i>one</i>	\$ 98.50 ✓
4	1 pc inlet manifold <i>one</i>	\$ 1,085.00 ✓
5	1 pc front wire harness <i>torn</i>	\$ 435.00 ✓
6	1 pc front fender innershield <i>torn</i>	\$ 122.00 ✓
		\$ 2,007.50
Less 20%		\$ (401.50)
		\$ 1,606.00