Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd

6 Raffles Quay #22-00

Singapore 048580

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 25 Oct 2024

Preliminary Advice

Vehicle No: SJQ4541XAccident Date: 21/10/2024Make: HYUNDAI AVANTEPolicy No.: D24MPC0003636

Assignment Date : 24/10/2024 Excess : \$\$0.00

Date of Inspection : 24/10/2024 Est. Duration of Repair : 6

Inspection At : BLUWEL AUTOMOTIVE SERVICE PTE LTD (HQ)

1 KAKI BUKIT AVENUE 6, #01-28/37/53/55/56 AÚTOBAY@KAKI BUKIT

SINGAPORE 417883

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,131.84
Revised Amount	:S\$	10,614.16
Check Items (Estimated)	:S\$	1,892.08
Total	:S\$	12,506.24

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	35,000.00
COE / PARF Rebate	:S\$	11,822.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,178,00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us
	have your authorisation.

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.