

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJ2 4541X
 at Workshop m/s 327
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: \$600
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \$35k
 IDAC Accident Rport: Consistent?: **Yes** or No
 GIA / PR Seen: Consistent?: **Yes** or No
 Est. Repairs: 6 days Res.: **Yes** or No
 Lum Sum: 20 % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 3502
 Vehicle: IN / OUT LTA11822

Veh No: SJ2 4541X Yr Regn: 13/05/09
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: Hyundai Avante c.c. 1591
 Colour: Black A/C: **Insured / Std / NI / NA**
 Sp.Reading: 172517 T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: KMHDU41BR9U758042
 Gen. Cond: **Good / Fair / Poor / Burnt**
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: **Nil / S/Rim / STD A/Rim** or

Tyre Size: F: _____
 R: 215-45-R17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Triangle

Front 5 mm R/Bal. 5 mm
 L/Bal. 5 mm Rear 5 mm
 D.O.A. 21/10/24 D.O.I. 24/10/24
 Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or
lap
 The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
22/11/24	Des 9k. Coe unbr 30.04-2029 Bal 4yrs 6mth L/S \$ 8900 insured Kenny (Red. \$ 7837.84, 46%)

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 6
 Resurvey No. of Trip: _____

1) _____
 Date/Time, File Return to?
 2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Report Format : _____
 Lump Sum / I.B.I: (\$) _____)

Survey Fee:	<div style="border: 1px solid black; width: 100%; height: 100%;"></div>
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	<div style="border: 1px solid black; width: 100%; height: 20px;"></div>



Reg. No.: 53191952L

KEC RECOVERY

Block 5 Upper Aljunied Lane #01-26 Singapore 360005

Tel: 6285 1151 Fax: 6285 7261

Email: s.kecrecovery@gmail.com

24 HRS HOTLINE: 8555 5229

CASH INVOICE
 WORK ORDER

No.: 42350

Date: 22/10/24

P.O.No: _____

Lessrs: _____

Owner / Member's name: _____ NRIC/Membership No: _____ Contact No: _____

Vehicle No: SJQ 4541X Model: KIA K3

From: 10 Kaki Bukit Rd 2 #01-18 To: Auto Bay #01-55

Tow Truck No: 7001

Request Cash: \$60+ Additional charges: _____ Tow Driver: Q

Order By: 84241433 Workshop Contact No: _____

Notes: _____


Time Received: _____ Time Arrived: _____ Time Left: _____ Time Completed: 1040

Additional Services:

- | | | | | |
|---------------------------------------|--|---|---|--|
| <input type="checkbox"/> Accident Veh | <input type="checkbox"/> Breakdown Veh | <input type="checkbox"/> Battery | <input type="checkbox"/> Escort / Standby | <input type="checkbox"/> Multi Storey Car Park |
| <input type="checkbox"/> King Dolly | <input type="checkbox"/> Flat Bed | <input type="checkbox"/> With Body Kit | <input type="checkbox"/> Door Opening Service | <input type="checkbox"/> Basement car Park |
| <input type="checkbox"/> Crane up | <input type="checkbox"/> Single Line Winch | <input type="checkbox"/> Jumpstart | <input type="checkbox"/> Tyre Replacement | <input type="checkbox"/> Veh on Offshore Islands |
| <input type="checkbox"/> With Load | <input type="checkbox"/> With Canopy | <input type="checkbox"/> With Freezer Box | <input type="checkbox"/> With Cargo Box | <input type="checkbox"/> Collect Documents / Ignit |
| <input type="checkbox"/> To and Fro | <input type="checkbox"/> Release Brakes | <input type="checkbox"/> Dismantle Shaft | <input type="checkbox"/> Transport Charged | <input type="checkbox"/> Handling Import / Export |
| <input type="checkbox"/> Others | <input type="checkbox"/> Call cancelled | <input type="checkbox"/> Sunday | <input type="checkbox"/> Public Holiday | <input type="checkbox"/> Midnight Charge |

Note: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

Tow Driver Signature



Customer's Signature

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	350E
Vehicle Details	
Vehicle No.:	SJQ4541X
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2024
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	G4FC9U653212
Chassis No.:	KMHDU41BR9U758042
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,465.00
Original Registration Date:	13 May 2009
First Registration Date:	13 May 2009
Transfer Count:	3
Actual ARF Paid:	\$2,068.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$26,175.00
COE Rebate Amount:	\$11,822.00
Total Rebate Amount:	\$11,822.00
Message	

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 24 Oct 2024

OK



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

4/5 \$8900

GST Reg No.: 200704951N

Co Reg No.: 200704951N

*not Authorized
in
name
90096608
24/10/24
Excess \$600
Wholesale Attorney*

Date: 23/10/2024

India International Insurance Pte Ltd
64 Cecil Street
#04/06 IOB Building
Singapore 049711

Policy No.: D24MPC003636
Vehicle No.: SJQ4541X
Model: HYUNDAI AVANTE
D.O.A 21/10/2024

6 days. 4/5 = 8900

Estimate Repair Cost For SJQ4541X

NO.	DESCRIPTIONS	AMOUNT
1	1 PC FRONT BUMPER	\$ 315 658.20 ✓
2	1 PC FRONT BUMPER TOP RUBBER SEAL	\$ AN 85.20 X
3	2 PCS FRONT BUMPER TOP BRACKET	\$ NS 197.20 X
4	2 PCS FRONT BUMPER RETAINER	\$ set 173.80 ✓
5	1 PC FRONT BUMPER SPONGE	\$ NF 225.60 X
6	1 PC FRONT BUMPER REINFORCEMENT	319.20 \$ set 589.50 ✓
7	1 PC FRONT BUMPER RADIATOR GRILLE	582.00 \$ cre 1,082.90 ✓
8	1 PC SUPPORT PANEL TOP GARNISH	\$ NS 202.50 X
9	1 PC FRONT SUPPORT PANEL	cro / \$ succ 987.50 ✓
10	2 PCS FRONT HEADLAMPS <i>98 x 2 = 1962</i>	\$ holder 3,512.80 ✓
11	1 PC FRONT BONNET	\$ succ 1,971.20 ✓
12	1 PC FRONT BONNET INSULATOR	241.20 \$ 24/10/24 385.90 ✓
13	1 PC RADIATOR	\$ 24/10/24 619.00 ✓
14	1 PC RADIATOR FAN MOTOR ASSY	\$ one part 596.00 ✓
15	1 PC RADIATOR TOP HOSE	\$ 701 42.00 ✓
16	1 PC RADIATOR BOTTOM HOSE	\$ 11 42.00 X
17	1 PC AIR CON CONDENSER	\$ set 991.00 ✓
18	1 PC AIR CON SUCTION PIPE	302.00 \$ set 648.00 ✓
19	1 PC AIR CON DISCHARGE PIPE	\$ set 192.00 X
20	1 PC NUMBER PLATE	\$ 320 30.00 ✓
		\$ 13,227.30
		LESS 20% \$ (2,645.46)
		\$ 10,581.84

MISC & LABOUR CHARGE

21	TOWING	\$ 200.00 <i>60</i>
22	REMOVE & REFIX FRONT UNDERCARRIAGE	\$ 400.00 X



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

NO.	DESCRIPTIONS	AMOUNT
23	REMOVE & REFIX FRONT PORTION, KNOCKING, WELDING, CUT & JACK	\$ 900 1,800.00
24	CHASSIS FRAME. ALIGNMENT	
25	RESPRAY FRONT PORTION. TOUCH-UP & POLISHING	\$ 900 1,500.00
	ELECTRICAL & FOCUS WIRING	\$ 20 50.00
26	COMPUTERIZE & 4 WHEELS ALIGNMENT	\$ 11 X 100.00
27	TO REMOVE & RFIX FRONT SUPPORT PANEL & HEADLAMP RH. ALIGNMENT	\$ refer note 400.00 X
28	REMOVE AIR CON & REFILL GAS	\$ 100.00 ✓
		<hr/> \$ 4,550.00
	TOTAL:	<hr/> \$ 15,131.84

LKK Auto Consultants hereby notify the Repairer of the following:

- To accurately estimate for repair work
- To identify damaged parts
- Parts prices are subject to change
- All parts survey is on a "Willed" basis
- No "tagged" modification is allowed
- Supplementary item(s) must be requested
- is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer
Signature:
Date:

7-1148260
202

9186.08
1980

11166.08
202

8932



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

Date: 14/11/2024

India International Insurance Pte Ltd

Policy No.: D24MPC003636

6 Raffles Quay

Vehicle No.: SJQ4541X

#22-00

Model: HYUNDAI AVANTE

Singapore 048580

D.O.A 21/10/2024

Estimate Repair Cost For SJQ4541X

Supplementary

NO.	DESCRIPTIONS	AMOUNT
1	1 pc bonnet lock <i>beat/cur</i>	\$ 97.00 ✓
2	2 pcs bonnet hinges <i>beat</i>	\$ 170.00 ✓
3	1 pc horn unit <i>one</i>	\$ 98.50 ✓
4	1 pc inlet manifold <i>one</i>	\$ 1,085.00 ✓
5	1 pc front wire harness <i>torn</i>	\$ 435.00 ✓
6	1 pc front fender innershield <i>torn</i>	\$ 122.00 ✓
		\$ 2,007.50
	Less 20%	\$ (401.50)
		\$ 1,606.00