

(08/11/13) wef

ASS. REC. BY: Marius

REF:

CS/11/24100422/Unp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: 5JQ 4541Xat Workshop m/s 3m

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: ?

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$35k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS3502

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 11822Veh No: 5JQ 4541X Yr Regn: 13/05/09Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Hyundai Avante c.c. 1591Colour: Black A/C: Insured / Std / NI / NASp. Reading: 172517 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHDL41BR9U758042Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 215-45-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TriangleFront 5 mm Rear 5 mmR/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 21/10/24 D.O.I. 24/10/24

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orlap

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Dep 9/12</u>
	<u>Complete 30-04-2029 1st 4 yrs 6mth</u>
	<u>45</u>

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	350E

Vehicle Details

Vehicle No.:	SJQ4541X
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2024
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	G4FC9U653212
Chassis No.:	KMH DU41BR9U758042
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,465.00
Original Registration Date:	13 May 2009
First Registration Date:	13 May 2009
Transfer Count:	3
Actual ARF Paid:	\$2,068.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Apr 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$26,175.00
COE Rebate Amount:	\$11,822.00
Total Rebate Amount:	\$11,822.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 24 Oct 2024

OK



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

*not Authorized
in
motor
90096608
24/10/24
541055
the whole thing
6 days. 4/5*

Date: 23/10/2024

India International Insurance Pte Ltd

Policy No.: D24MPC003636

64 Cecil Street

Vehicle No.: SJQ4541X

#04/06 IOB Building

Model: HYUNDAI AVANTE

Singapore 049711

D.O.A 21/10/2024

Estimate Repair Cost For SJQ4541X

NO.	DESCRIPTIONS	AMOUNT
1	1 PC FRONT BUMPER	\$ 715 658.20 ✓
2	1 PC FRONT BUMPER TOP RUBBER SEAL	\$ 85.20 ✓
3	2 PCS FRONT BUMPER TOP BRACKET	\$ 197.20 ?
4	2 PCS FRONT BUMPER RETAINER	\$ 173.80 ✓
5	1 PC FRONT BUMPER SPONGE	\$ 225.60 ✓
6	1 PC FRONT BUMPER REINFORCEMENT	\$ 589.50 ✓
7	1 PC FRONT BUMPER RADIATOR GRILLE	\$ 1,082.90 ?
8	1 PC SUPPORT PANEL TOP GARNISH	\$ 202.50 X
9	1 PC FRONT SUPPORT PANEL	\$ 987.50 ✓
10	2 PCS FRONT HEADLAMPS	\$ 3,512.80 ✓
11	1 PC FRONT BONNET	\$ 1,971.20 ✓
12	1 PC FRONT BONNET INSULATOR	\$ 385.90 ✓
13	1 PC RADIATOR	\$ 619.00 ✓
14	1 PC RADIATOR FAN MOTOR ASSY	\$ 596.00 ✓
15	1 PC RADIATOR TOP HOSE	\$ 42.00 ✓
16	1 PC RADIATOR BOTTOM HOSE	\$ 42.00 X
17	1 PC AIR CON CONDENSER	\$ 991.00 ✓
18	1 PC AIR CON SUCTION PIPE	\$ 643.00 ?
19	1 PC AIR CON DISCHARGE PIPE	\$ 192.00 ?
20	1 PC NUMBER PLATE	\$ 30.00 ✓
		\$ 13,227.30
LESS 20%		\$ (2,645.46)
		\$ 10,581.84

MISC & LABOUR CHARGE

21	TOWING	\$ 200.00 ?
22	REMOVE & REFIX FRONT UNDERCARRIAGE	\$ 400.00 X



BLUWEL AUTOMOTIVE SERVICE PTE LTD

1 Kaki Bukit Ave 6 Blk C #01-28/53/55/56 Singapore 417883

Tel: 67452088 Fax: 68412088

E-mail: bluwel2088@yahoo.com.sg

GST Reg No.: 200704951N

Co Reg No.: 200704951N

NO.	DESCRIPTIONS	AMOUNT
23	REMOVE & REFIX FRONT PORTION, KNOCKING, WELDING, CUT & JACK	\$ 900 1,800.00
24	CHASSIS FRAME. ALIGNMENT	
25	RESPRAY FRONT PORTION. TOUCH-UP & POLISHING	\$ 900 1,500.00
	ELECTRICAL & FOCUS WIRING	\$ 20 50.00
26	COMPUTERIZE & 4 WHEELS ALIGNMENT	\$ 11 X 100.00
27	TO REMOVE & RFIX FRONT SUPPORT PANEL & HEADLAMP RH. ALIGNMENT	\$ refer main 400.00 X labor
28	REMOVE AIR CON & REFILL GAS	\$ 100.00 ✓
		\$ 4,550.00
	TOTAL:	\$ 15,131.84

LKK Auto Consultants hereby notify the Repairer of the following:

- To rectify before returning vehicle
- To display damaged parts to the repairer
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be rectified and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: