

PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H




PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H






PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H






PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H




PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H




PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H




PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 22 of 28)


PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H




PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H



PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 28 of 28)

PHOTOGRAPHS FOR VEHICLE NO. : GBL 822H

