

Insurer Reference: DMCVSNA00027282400
 Repairer Reference: 073554
 Date calculated: 05/03/2025 10:58 AM

Full Report
 Registration: GBL822H
 Printed: 05/03/2025 11:00 AM

Code		Description	Part Number	Part Source	Price SGD
4451	(Supp) ---	AIR CONDITIONING	87050 26200	Original / BR	2,050.00
1392		AIR GUIDE TRIM	55708 26130	Original	290.00
3015		BADGE TOYOTA	90975 02086	Original	40.00
4414		BLOWER MOTOR	87103 26101	Original	640.00
0471		BONNET	53301 26090	Original	425.00
4465		CONDENSER	88450 26120	Original	730.00
1005		COOLING COIL	COOLING COIL	Original	2,250.00
1321		ENGINE FIREWALL	55015 26790	Original	1,580.00
7783		FAN MOTOR CPL	16360 30023	Original	1,270.00
0281		FRONT BUMPER	52119 26670	Original	255.00
1000		FRONT RIGHT AIR BAG	F/R AIR BAG	Original	1,350.00
1413		FRONT SCREEN SPACER	56115 26060	Original	0.00
1012		FRT AIR DUCT	FRT AIR DUCT	Original	95.00
0331		FRT BUMPER SUPPORT	52131 26060	Original	160.00
1015		FRT LOCK CARRIER CPL	53201 26100	Original	185.00
1019		FRT LWR CROSSMEMBER	57104 26201	Original	160.00
1320		FRT LWR CROSSMEMBER	57109 26041	Original	185.00
1003		FRT PANEL C-MEMBER	57053 26040	Original	100.00
0341		FT BUMPER AIR GRILLE	53112 26080	Original	80.00
0413		GRILLE BACKING	53112 26100	Original	320.00
0431		GRILLE BADGE	90975 02176	Original	40.00
4959	(Supp) ---	HEADLINING 2	63312 26161B1	Original cru	1,050.00
8739		HEAT EXCHANGER	17940 30051	Original	770.00
4330		INSTR PANEL SUPPORT	55330 26330	Original	500.00
4331		INSTRUMENT PANEL	55300 26150B0	Original	665.00
7358		INTERM FLANGE GEAR	45380 26061	Original	510.00
7201		L/FR WHEEL	42611 26152	Original	280.00
2287		L/INNER B-PILLAR	61038 26010	Original	295.00
1887		L/INNER DOOR HANDLE	69208 26010B1	Original	85.00
1747		L/INNER MIRROR TRIM	67492 26050	Original	75.00
3717		L/LOWER ROLLER ARM	68360 26130	Original	190.00
1513		L/LWR DOOR SEAL	67864 26010	Original	70.00
2277		L/OUTER B-PILLAR	61312 26120	Original	295.00
2395		L/OUTER ROOF FRAME	61226 26010	Original	175.00
1891		L/R DOOR LOCK	69340 26050	Original	210.00
1889		L/R LOCK MOTOR	69640 26342	Original	290.00
3481		L/RR SIDE PANEL	61612 26520	Original	730.00
3845		L/R SIDE WINDOW	62740 26B80	Original	400.00
1809		L/R SLDG DOOR SEAL	67872 26020	Original	240.00
1781		L/R SLIDING DOOR	67004 26670	Original	830.00
2147		L/R STEP	58304 26550	Original	280.00
3863		L/R WDW BONDING KIT	KNGKWI1		0.00
2621		L/SIDE SUPPORT	52156 26010	Original	25.00
3695		L/UPPER GUIDE RAIL	68309 26031	Original	175.00
3715		L/UPPER ROLLER ARM	68320 26031	Original	60.00
1813		L/UPP SLDG DOOR SEAL	67888 26020	Original	55.00
0475		LEFT BONNET HINGE	53420 26040	Original	40.00
4969		LEFT C-PILLAR	61384 26020	Original	550.00
0561		LEFT HEADLAMP ASSY	81170 26741	Original	420.00
0410		LWR RADIATOR GRILLE	53111 26550	Original	255.00
4411	(Supp) ---	LWR WARM AIR HOUSING	87130 26220	Original BR	420.00
1011		R/L DOOR RAIL	R/L DOOR RAIL	Original	280.00
1010		R/L WIN GLASS	R/L WIN GLASS	Original	400.00
1514		R/LWR DOOR SEAL	67863 26010	Original	70.00
3482		R/RR SIDE PANEL	61611 0L010	Original	730.00

Insurer Reference: DMCVSNA00027282400
 Repairer Reference: 073554
 Date calculated: 05/03/2025 10:58 AM

Full Report
 Registration: GBL822H
 Printed: 05/03/2025 11:00 AM

Code	Description	Part Number	Part Source	Price SGD
7761	RADIATOR	16400 11A40	Original	980.00
3160	REAR SCREEN BOND KIT	PZ49I 00C1131	Original	0.00
1482	RIGHT FRONT DOOR	67001 26312	Original	800.00
0562	RIGHT HEADLAMP ASSY	81130 26741	Original	420.00
2351	ROOF	63111 26490	Original	3,800.00
4484	RR COMPR/EVAPOR PIPE	88717 2F670	Original	390.00
4485	RR COND/EVAPOR PIPE	88716 2N140	Original	395.00
7435	(Supp) --- SLIP RING	84306 26120	Original Nec	480.00
0411	UPP RADIATOR GRILLE	53111 26540	Original	200.00
1401	WINDSCREEN	56101 26022	Original	550.00
1411	WINDSCREEN BOND KIT	PZ49I 00C1131	Original	0.00
1423	WINDSCREEN MOULDING	75531 26081	Original	60.00

f: OEM Parts	Savings	0.00
n: Non-OEM Parts	Subtotal	32,870.00
u: Used parts	Total	32,870.00

Final Calculation

	SGD	SGD
Parts	32,870.00	
Total Parts		32,870.00
Labour Time Base 10 WU/h		
Total 916.0 WU X 42.00 SGD/h	3,847.20	
Total of Labour		3,847.20
Paint Work Time Base 10 WU/h		
Labour Cost 408.0 WU X 42.00 SGD/h	1,713.60	
Material Cost	680.82	
Total Paint Including Material		2,394.42
Repair Cost Excludes GST		39,111.62
GST (+9.00%)		3,520.05
Repair Cost Included GST		42,631.67
Deductions (Excludes GST)		
Repair Cost Discount (+20.00%)	-7,822.32	
Total Of Deductions (Excludes GST)		-7,822.32
Grand Total Excludes GST		31,289.30
GST (+9.00%)		2,816.04
Grand Total Included GST		34,105.34

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Ding Auto Pte Ltd

PARTS SUPPLEMENTARY & QUOTATION FORM

ATTENTION: <u>STEVE (LKK)</u>	
VEHICLE NUMBER: <u>G18L8J2H</u>	WORK ORDER NUMBER:
MAKE & MODEL: <u>TOYOTA HIACE</u>	OUR REFERENCE NUMBER: <u>G18L8J2H</u>

S/NO	PART NUMBER	PART DESCRIPTION	QTY	LIST / COST PRICE	SURVEYOR REMARK	W/S REMARK
1		FRONT CROSSMEMBER	1	\$1,250.00	/ BT	
2		FRONT LOWER ARM RHS	1	\$190.00	/ BT	
3		FRONT LOWER ARM BAR RHS	1	\$90.00	/ BT	
4		STEERING RACK	1	\$1,200.00	x nn	
5		ACI-BLUE SENSOR	1	\$	x nn	
6						
7						
8						
9						
10						
11						
12						
13						

S/NO	SPECIAL NETT / LABOUR / SPRAY PAINT	PRICE	SURVEYOR REMARK	W/S REMARK
1	Wheel Alignment	\$80.00	/ Nec	
2				
3				

ESTIMATOR: Lynn Tan



Steve (LKK)
12/03/25, 4.30 pm

SURVEYOR: Steve (LKK)