

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	MS FIRST CAPITAL		Ref:	CS/FCI24100425/Avp3e2
	16 RAFFLES QUAY		Date:	11/11/2024
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2
	SINGAPORE 04050			
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHA 4588U	Veh. Inspected	SNR 3100P
	Policy No.	D-24101861MFCT	Coverage	0
	Claim No.	D24009333MFCT	Excess	\$0.00
	Assign From	JOANNE	Assign Date	24/10/2024
2. Vehicle Details				
	Make & Model	HONDA VEZEL	C.C	1496
	Engine No.	L15B4032814	Year of Reg.	20/05/2016
	Chassis No.	RU11112806	Colour	BLACK
	Odometer	128098 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM	•	
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	215/60 R16	YOKOHAMA	6
	L/H Front Tyre	215/60 R16	YOKOHAMA	6
	R/H Rear Tyre	215/60 R16	YOKOHAMA	6
	L/H Rear Tyre	215/60 R16	YOKOHAMA	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	22/10/2024	Inspection Date	23/10/2024
	Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**Estimate Days of Repair**