

AES. REC. BY:

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL11084X

Yr Regn:

2017, Feb.

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Audi A3.

C.C

999

Colour

Black.

A/C:

Insured / Std / NI / NA

Sp. Reading

225490

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZ8V3H1031358

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

205/55R16.

R:

205/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

26/06/24

Survey held at

JL Perfect

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Lon Pac.

MV:

PV:

Nett:

903D

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Week end (\$

Report Format:

Lump Sum / L&M:

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 25.06.2024

TO : LONPAC MOTOR CLAIMS DEPTS
VEHICLE NO : SLL1084X
MODEL : AUDI A3
DATE OF ACCIDENT : 17.06.2024
TIME OF ACCIDENT : 13:00 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehnd</i>	1	\$ 1,043.73	\$ 1,043.73
2	REAR BUMPER (LOWER) <i>cut</i>	1	\$ 436.54	\$ 436.54
3	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 87.60	\$ 87.60
4	REAR BUMPER REFLECTOR <i>RTA included</i>	2	\$ 159.72	\$ 319.44
5	REAR BUMPER CENTER GARNISH <i>crushed</i>	1	\$ 498.42	\$ 498.42
6	REAR BUMPER CENTER LOWER BRACKET <i>new</i>	2	\$ 56.30	\$ 112.60
7	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 48.61	\$ 97.22
8	REAR BUMPER CORNER BRACKET <i>new</i>	2	\$ 54.41	\$ 108.82
9	REAR BUMPER REINFORCEMENT <i>Dehnd</i>	1	\$ 675.28	\$ 675.28
10	REVERSE CAMERA <i>new</i>	1	\$ 1,638.00	\$ 1,638.00
11	REVERSE SENSOR <i>2 pieces damaged</i>	4	\$ 279.53	\$ 1,118.12
12	REVERSE SENSOR HOLDER <i>new</i>	4	\$ 72.31	\$ 289.24
13	REVERSE SENSOR WIREHARNES <i>snapped</i>	1	\$ 1,493.78	\$ 1,493.78
14	REAR FENDER COWLING <i>2nd</i>	2	\$ 249.31	\$ 498.62
15	REAR FENDER INNER TRIM <i>new</i>	2	\$ 690.21	\$ 1,380.42
16	BOOT LID <i>2 Buckleed</i>	1	\$ 1,998.85	\$ 1,998.85
17	BOOT LID LAMP <i>RTA cut</i>	2	\$ 419.60	\$ 839.20
18	BOOT LID LOGO <i>new</i>	1	\$ 108.33	\$ 108.33
19	BOOT LID EMBLEM 'TFSI' <i>new</i>	1	\$ 83.33	\$ 83.33
20	BOOT LID EMBLEM 'A3' <i>new</i>	1	\$ 87.35	\$ 87.35
21	BOOT LID TOP LOCK <i>new</i>	1	\$ 254.28	\$ 254.28

✓
✓
+
159.72
✓
+
+
+
✓
+
500
+
450
+
+
419.60
+
+
+
+

TO : **LONPAC** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLL1084X**
 MODEL : **AUDI A3**
 DATE OF ACCIDENT : 17.06.2024
 TIME OF ACCIDENT : 13:00 HOURS

22	BOOT LID LOWER LOCK	2	\$ 74.32	\$ 74.32
23	BOOT LID DETECTOR	1	\$ 238.60	\$ 238.60
24	BOOTLID WEATHERSTRIP	1	\$ 169.28	\$ 169.28
25	TAILLAMP	2	\$ 598.51	\$ 1,197.02
26	REAR END PANEL	1	\$ 1,294.82	\$ 1,294.82
27	REAR END PANEL TOP GARNISH	1	\$ 252.91	\$ 252.91
28	REAR FLOOR PANEL TOP BOARD	1	\$ 589.30	\$ 589.30
29	REAR TOOLS COMPARTMENT (SPONGE)	1	\$ 397.21	\$ 397.21

TOTAL PRICE \$ 17,382.63
 LESS 5% \$ 869.13
SUB TOTAL PRICE \$ 16,513.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00
3	REAR BUMPER (LOWER) CLIP (SET)	1	\$ 50.00	\$ 50.00
4	REAR BUMPER CENTER GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
5	REAR FENDER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00
6	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 80.00	\$ 80.00
7	TAILLAMP CLIP (SET)	1	\$ 50.00	\$ 50.00
8	BOOT LID SEALANT	1	\$ 150.00	\$ 150.00
9	BOOT LID INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00
10	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
11	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00

TOTAL \$ 780.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	600
3	TUFF COAT	\$ 250.00	60

TO : **LONPAC** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLL1084X**
MODEL : **AUDI A3**
DATE OF ACCIDENT : 17.06.2024
TIME OF ACCIDENT : 13:00 HOURS

4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	X
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 680.00	X 180

TOTAL \$5,220.00

ESTIMATE REPORT

TOTAL PARTS COST \$ 17,293.50
TOTAL LABOUR COST : \$ 5,220.00
TOTAL REPAIR COST : \$ 22,513.50

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/S 26/06/24
06 days