

Not Authorized
in
morans
30/10/24
t/s # 3300
Take photo. At the top.
4 days.

S/N.	Item Description		Amount (\$)
1	Rear Boot	2159.10	\$ 2,377.00
2	Rear Boot Toyota Logo	11	\$ 76.10
3	Rear Boot Absorber x 2 pcs	11	\$ 952.14
4	Rear Boot Rear View Mirror	280.10	\$ 334.60
5	Rear Boot Lock	Dange / Jan	\$ 393.63
6	Rear Boot Lock Protector	SM	\$ 89.70
7	Rear Boot Catch	11	\$ 127.40
8	Rear Boot Stopper x 2 pcs	11	\$ 219.65
9	Rear Boot Stopper Cushion x 2 pcs	11	\$ 97.61
10	Rear Number Plate Top Garnish	Che	\$ 302.68
11	Rear Number Plate Lamp x 2 pcs	11	\$ 325.58
12	Rear Boot Weatherstrip	11	\$ 564.28
13	Rear Boot Inner Trimboard Clip x 1 set	11	\$ 50.00
14	Taillamp x 2 pcs	388.00 x 2 = 776.00	\$ 947.89
15	Taillamp Clip x 2 set	11	\$ 80.00
16	Rear Bumper	11	\$ 910.80
17	Rear Bumper Side Retainer x 2 pcs	11	\$ 81.40
18	Rear Bumper Center Bracket x 4 pcs	11	\$ 158.40
19	Rear Bumper Clip x 1 set	11	\$ 50.00
20	Rear Corner Garnish x 2 pcs	11	\$ 189.40
21	End Panel (Inner)	11	\$ 804.10
22	End Panel (Outer)	R	\$ 270.20
23	Rear Step Panel	11	\$ 266.40
24	End Panel Top Scuff Plate	11	\$ 219.40
25	Rear Fender (LH)	R	\$ 2,359.50
	Total :	\$	
	Less 25% :	\$	
	Amount :	\$	

S/N	Special Nett Item	Amount (\$)
1	Reverse Sensor x 2 pcs <i>SCU</i>	\$ 280.00
2	"Hiace" Sticker <i>neu</i>	\$ 30.00
3	"8 Pax" Sticker <i>neu</i>	\$ 30.00
4	"1200kg" Sticker <i>neu</i>	\$ 30.00
5	70KM/H Sticker <i>neu</i>	\$ 30.00
6	Lalamove Sticker <i>neu</i>	\$ 120.00
7	Rear Windscreen Sealant <i>neu</i>	\$ 80.00
8	End Panel Sealant <i>11</i>	\$ 80.00
9	Rear Number Plate Garnish Chrome <i>SCU</i>	\$ 180.00
10	Rear View Camera <i>11</i>	\$ 350.00
Amount :		\$ 1,210.00

X
✓ S/N
10 S/N
✓ S/N
10 S/N
X
40 S/N
X
X
X

Labour	Amount (\$)
To check rear wiring system	\$ 80.00
To remove & install reverse sensors	\$ 11 120.00
To remove & install rear interior garnishes, and trims to facilitate	\$ 11 280.00
To remove & reinstall rear windscreen	\$ 150.00
To transfer rear boot components from old boot to new boot	\$ 150.00
To apply anti-rusting coating on panels	\$ 280.00
Labour to remove, cut, change & panel beating	\$ 1,500.00
To putty and respray affected areas	\$ 1,800.00
Labour Total :	\$ 4,360.00
Total (Parts & Labour) \$	

20
X
X
100
50
30
400
500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 398761
252
2990.71
120
1100
4210.71
202
3368