

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/EG/24100426/Unp3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBG 3391Rat Workshop m/s Tichha' 12pm.

of _____

Insured: YP8507Y

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**Bal. or Market Value: \$38k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No 18?Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

32806
Vehicle: IN / OUTDate: _____ Person Contacted: LYA 8316Veh No: GBG 3391R Yr Regn: 20/07/17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CMMake: Toyota piece 3.0M c.c. 2982Colour: white A/C: Insured / Std / NI / NASp. Reading: 287984 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KDH 2015026726Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185-R 15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Agilis

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/10/24 D.O.I. 30/10/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Day 13k.

13-11-24 have video at folder
4/5 83300 in hand Robert (Red, \$11455.90, 77%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to?

Transportation: _____

2)

Add Fee: ☐ : Site Insp (\$) S + RS, SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$)

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 280B

Vehicle Details

Vehicle No.: GBG3391R
Vehicle to be Exported: No
Intended Deregistration Date: 30 Oct 2024
Vehicle Make: TOYOTA
Vehicle Model: HIACE 3.0 M
Primary Colour: White
Manufacturing Year: 2017
Engine No.: 1KD2693909
Chassis No.: KDH2015026726
Maximum Power Output: -
Open Market Value: \$31,591.00
Original Registration Date: 20 Jul 2017
First Registration Date: 20 Jul 2017
Transfer Count: 1
Actual ARF Paid: \$1,580.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 19 Jul 2027
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$30,600.00
COE Rebate Amount: \$8,316.00
Total Rebate Amount: \$8,316.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.


The information contained herein is correct as at 30 Oct 2024

OK



Home Used Cars-Listing

All Category



Search

Save Search



Any status x 2017 x

Sort by Any Status, Date Posted (Newest)

58 Vehicles

Car Make

Car Model

Price Range

Depreciation

2017

Mileage



Toyota Hiace 3.0A \$43,800 \$16,740 /yr 13-Jun-2017 (2yrs 7mths COE left) 2,982 cc 2 Owners Diesel

5 door with Rear Aircon. Extremely good well maintained by owner. View to believe. Call for a test drive now.

Ezy-1 Pte Ltd|Posted 30-Oct-2024 Compare

PREMIUM AD



Toyota Hiace 3.0M DX \$38,800 \$12,680 /yr 22-Nov-2017 (3yrs COE left) 196,700 km 2,982 cc 1 Owner

1st owner unit since registration. No repair needed. Come view to believe! High loan applicable and trade in acceptable. First come first come basis. Please contact our friendly sales consultant for a viewing appointment before it is gone. Strictly for appointment only!

Think One Automobile & Trading|Posted 30-Oct-2024 Compare

PREMIUM AD



Toyota Hiace 3.0M \$34,800 \$14,550 /yr 23-Mar-2017 (2yrs 4mths COE left) 182,000 km 2,982 cc 1 Owner

1 owner unit since registration. No repair needed. Come view to believe! High loan applicable and trade in acceptable. Contact our sales team now!

Think One Automobile & Trading|Posted 30-Oct-2024 Compare

PREMIUM AD



Toyota Hiace 3.0M \$41,800 \$13,720 /yr 17-Nov-2017 (3yrs COE left) 2,982 cc 1 Owner Diesel

Pre-owned Toyota hiace agent unit! Super good good condition! Powerful & healthy engine! High loan available, high trade in. Hurry call to view and test drive now!

SG Motor Link Pte Ltd|Posted 29-Oct-2024 Compare

PREMIUM AD

Compare

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 48992400W

Vehicle Number: GBG3391R
Vehicle Model : Toyota Hiace 3.0 M
Manufacturing Year : 2017
Chassis : KDH2015026726

Not Authorized
 in
 motor
 30/10/24
 1/s # 3300/
 Take photo of the car
 4 days

S/N.	Item Description	Amount (\$)
1	Rear Boot 2159.10 2013014	\$ 2377.00
2	Rear Boot Toyota Logo 122	\$ 76.10
3	Rear Boot Absorber x 2 pcs 11	\$ 952.14
4	Rear Boot Rear View Mirror 280.10 5120	\$ 334.60
5	Rear Boot Lock Damage/1m	\$ 393.63
6	Rear Boot Lock Protector 511	\$ 89.70
7	Rear Boot Catch 11	\$ 127.40
8	Rear Boot Stopper x 2 pcs 11	\$ 219.65
9	Rear Boot Stopper Cushion x 2 pcs 11	\$ 97.61
10	Rear Number Plate Top Garnish 11	\$ 302.68
11	Rear Number Plate Lamp x 2 pcs 11	\$ 325.58
12	Rear Boot Weatherstrip 11	\$ 564.28
13	Rear Boot Inner Trimboard Clip x 1 set 11	\$ 50.00
14	Taillamp x 2 pcs 388.00 x 2 = 776.00 11	\$ 947.89
15	Taillamp Clip x 2 set 11	\$ 80.00
16	Rear Bumper 11	\$ 910.80
17	Rear Bumper Side Retainer x 2 pcs 11	\$ 81.40
18	Rear Bumper Center Bracket x 4 pcs 11	\$ 158.40
19	Rear Bumper Clip x 1 set 11	\$ 50.00
20	Rear Corner Garnish x 2 pcs 11	\$ 189.40
21	End Panel (Inner) 11	\$ 804.10
22	End Panel (Outer) 11	\$ 270.20
23	Rear Step Panel 11	\$ 266.40
24	End Panel Top Scuff Plate 11	\$ 219.40
25	Rear Fender (LH) 11	\$ 2,359.50
Total :		\$ 12247.86
Less 25% :		\$ 9185.90
Amount :		\$

S/N	Special Nett Item	Amount (\$)
1	Reverse Sensor x 2 pcs <i>SCU</i>	\$ 280.00
2	"Hiace" Sticker <i>neu</i>	\$ 30.00
3	"8 Pax" Sticker <i>neu</i>	\$ 30.00
4	"1200kg" Sticker <i>neu</i>	\$ 30.00
5	70KM/H Sticker <i>neu</i>	\$ 30.00
6	Lalamove Sticker <i>neu</i>	\$ 120.00
7	Rear Windscreen Sealant <i>neu</i>	\$ 80.00
8	End Panel Sealant <i>neu</i>	\$ 80.00
9	Rear Number Plate Garnish Chrome <i>SCU</i>	\$ 180.00
10	Rear View Camera <i>neu</i>	\$ 350.00
Amount :		\$ 1,210.00

X
✓ S/N
10 S/N
✓ S/N
10 S/N
X
40 S/N
X
X
X

Labour	Amount (\$)
To check rear wiring system	\$ 80.00
To remove & install reverse sensors	\$ 11 120.00
To remove & install rear interior garnishes, and trims to facilitate	\$ 11 280.00
To remove & reinstall rear windscreen	\$ 150.00
To transfer rear boot components from old boot to new boot	\$ 150.00
To apply anti-rusting coating on panels	\$ 280.00
Labour to remove, cut, change & panel beating	\$ 1,500.00
To putty and respray affected areas	\$ 1,800.00
Labour Total :	\$ 4,360.00
Total (Parts & Labour)	\$ 14755.90

20
X
X
100
50
30
400
500

P- 398761
252
2990.71
120
1100
4210.71
202
3368

LIK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, for one week
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____