

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: jin@jinauto.com.sg

Company Reg No: 200704370C , GST Reg No : 200704370C

Date 24-10-24

M/S Great American Insurance Company

ESTIMATE REPAIR COST FOR CB8076H

S/N	QTY	DESCRIPTION		\$
1	1 PC	FRT BUMPER <i>Re</i>		300.00 ✓
2	2 PC	FRT BUMPER SIDE RETAINER - 11		60.00 X
3	1 PC	FRT BUMPER REINFORCEMENT 11		150.00 X
4	1 PC	FRT HEADLAMP - RH 11		220.00 X
5	1 PC	FRT HEADLAMP - LH 11		220.00 X
6	1 PC	REAR WINDSCREEN <i>shatter</i>		600.00 ✓
7	1 PC	REAR WINDSCREEN MOULDING NS		60.00 X
8	1 PC	TAILGATE <i>300.00</i>		900.00 ✓
9	1 PC	TAILGATE INNER TRIMBOARD <i>see</i>		150.00 X
10	1 PC	REAR TOP MIRROR <i>one</i>		160.00 ✓
11	1 PC	TAILGATE LOCK <i>2000/500</i>		110.00 ✓
12	1 PC	TAILGATE WEATHERSTRIP RUBBER <i>see</i>		180.00 X
13	1 PC	TAILGATE NUMBER PLATE TOP BLACK GARNISH <i>ground</i>		80.00 ✓
14	1 PC	REAR BUMPER <i>D.S</i>		500.00 ✓
15	2PC	REAR BUMPER SIDE RETAINER - 11		60.00 X
16	1 PC	END PANEL (INNER) <i>300.00</i>		450.00 ✓
17	1 PC	END PANEL (OUTER) <i>300.00</i>		250.00 ✓
18	4 PCS	END PANEL BRACKETS <i>one</i>		200.00 ✓
19	1 PC	END PANEL TOP METAL PLATE 11		100.00 X
20	1 PC	END PANEL TOP GARNISH 11		200.00 X
21	1 PC	LH TAILAMP <i>one</i>		190.00 ✓
22	1 PC	LH TAILAMP PANEL <i>1</i>		60.00 X
23	1 PC	RH TAILAMP <i>one</i>		190.00 ✓
24	1 PC	RH TAILAMP PANEL <i>1</i>		60.00 X
25	1 PC	TOYOTA EMBLEM <i>new</i>		40.00 ✓
26	1 PC	TAILGATE "TOYOTA" STICKER <i>new / kir</i>		25.00 X
27	1 PC	REAR "HIACE" STICKER <i>new / kir</i>		25.00 X
28	1 PC	TAILGATE LOCK <i>repair</i>		110.00 X
29	1 PC	TAILGATE LOCK BRACKET 11		50.00 X
30	1 PC	REAR WIPER ARM <i>11</i>		70.00 X
31	1 PC	REAR WIPER BLADE <i>11</i>		45.00 X
32	1 PC	REAR WIPER MOTOR <i>11</i>		255.00 X
				\$ 6,070.00
			add 20%	\$ 1,214.00
				\$ 7,284.00

*Not Authorized
new
marks
179008608
24/10/24
1/s #60001
John the. the. 111.
7 days.*

		Bal c/f	\$ 7,284.00
33	1 SET	CLIPS rear bumper <i>ner</i>	\$ 100.00 <i>40 5/10</i>
34	1 SET	SEALANT & GUM <i>ner</i>	\$ 80.00 <i>40 11</i>
35	1 SET	REVERSE SENSOR <i>ene</i>	\$ 280.00 <i>200 ..</i>
36	1 PC	REAR NUMBER PLATE <i>Bert</i>	\$ 35.00 <i>30 --</i>
37	1 PC	70 KM/H STICKER <i>ner</i>	\$ 20.00 <i>10 --</i>
38		WIRING	\$ 50.00 <i>- 30</i>
39		SPRAY PAINTING	\$ 1,200.00 <i>800</i>
40		LABOUR CHARGE	\$ 1,600.00 <i>1000</i>
41		LABOUR FOR REVERSE SENSOR	\$ 60.00 <i>30</i>
42		LABOUR TO REMOVE & REFIT REAR WINDSCREEN	\$ 120.00 <i>100</i>
43		TUFF KOTE	\$ 120.00 <i>50</i>
44		REMOVE & REFIT SEATS ETC FACILITATE REPAIR JOB	\$ 280.00 <i>80</i>
			<u>\$ 11,229.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3970
+ 202
4764.00
320
290
7174
15%
6000