



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

TP China
Xiao Chang

WOODLANDS 11 CAR RENTAL PTE LTD
11 WOODLANDS CLOSE #03-17B WOODLANDS
11
SINGAPORE 737853

TAX INVOICE

Repair Code : CLM18433

Date in : 23/10/2024

Vehicle Num. : GBK1145C

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2012009574/1GD8495619

Contact : 86912787 85748408

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Disturbed</i>	1	673.10	✓ 673.10
REAR BUMPER LOWER BRACKET <i>3 pieces damaged</i>	4	48.00	<i>75</i> 192.00
REAR BUMPER SIDE RETAINER L/R <i>Ambed</i>	2	47.00	✓ 94.00
REAR END PANEL (INNER) <i>Disturbed</i>	1	820.70	✓ 820.70
REAR END PANEL (OUTER)	1	743.00	✓ 743.00
REAR EXHAUST SILENCER BOX <i>Bent</i>	1	596.00	✓ 596.00
REAR EXHAUST SILENCER BOX RUBBER MOUNTING <i>new</i>	1	60.00	+ 60.00
REAR FLOOR PANEL <i>Regr</i>	1	1650.00	<i>X</i> 1,650.00
REAR FLOOR PANEL TOP PLATE <i>Bent</i>	1	195.00	✓ 195.00
REAR FLOOR PANEL TOP PLATE SIDE COVER L/R <i>new</i>	2	88.00	+ 176.00
REAR MECHANISM LOCK COVER <i>Ambed</i>	1	123.20	✓ 123.20
REAR RH FENDER <i>Regr</i>	1	2315.40	+ 2,315.40
REAR RH FENDER AIR VENT <i>Disturbed</i>	1	97.00	✓ 97.00
REAR RH FENDER INNER PANEL <i>Regr</i>	1	977.00	+ 977.00
REAR RH TAILLAMP INNER PANEL <i>Disturbed</i>	1	771.60	<i>48</i> ✓ 771.60
REAR RH TAILLAMP LOWER GARNISH <i>Disturbed</i>	1	157.00	✓ 157.00
REAR RH TAILLAMP LOWER GARNISH RETAINER <i>Ambed</i>	1	53.00	<i>30</i> ✓ 53.00
REAR SPARE TYRE CARRIAGE <i>Bent</i>	1	519.00	<i>375</i> ✓ 519.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

WOODLANDS 11 CAR RENTAL PTE LTD
 11 WOODLANDS CLOSE #03-17B WOODLANDS
 11
 SINGAPORE 737853

Contact : 86912787 85748408

TAX INVOICE

Repair Code : CLM18433

Date in : 23/10/2024

Vehicle Num. : GBK1145C

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2012009574/1GD8495619

REAR SPARE TYRE CARRIAGE BRACKET <i>new</i>	1	79.00	+	79.00
REAR STEP PANEL <i>But</i>	1	175.40	✓	175.40
REAR TAILGATE <i>Painted</i>	1	3045.60	2850	3045.60
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	63.00	✓	63.00
REAR TAILGATE DAMPER L/R <i>3 new</i>	2	214.00	+	428.00
REAR TAILGATE HINGES L/R	2	67.00	+	134.00
REAR TAILGATE INNER LOWER SIDE MOULDING L/R <i>new</i>	2	17.00	+	34.00
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i>	2	17.00	+	34.00
REAR TAILGATE INNER TRIM BOARD <i>new</i>	1	469.00	+	469.00
REAR TAILGATE LOCK STRIKER <i>new</i>	1	53.00	+	53.00
REAR TAILGATE MECHANISM LOCK <i>Painted</i>	1	264.00	✓	264.00
REAR TAILGATE OUTER GARNISH <i>new</i>	1	151.20	+	151.20
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	391.00	✓	391.00
REAR TAILLAMP L/R <i>Painted</i>	2	458.10	790	916.20
Subtotal before discount				16,450.40
Percentage discount 25%				4,112.60
Sub-total 1				12,337.80
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	30	80.00

*** This is a computer-generated document which requires no signature.***

Faki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

WOODLANDS 11 CAR RENTAL PTE LTD
 11 WOODLANDS CLOSE #03-17B WOODLANDS
 11
 SINGAPORE 737853

Contact : 86912787 85748408

TAX INVOICE

Repair Code : CLM18433
 Date in : 23/10/2024
 Vehicle Num. : GBK1145C
 Model : TOYOTA HIACE DX 2.8 AUTO
 Chassis/Eng# : GDH2012009574/1GD8495619

REAR BUMPER REVERSE SENSOR - SET <i>new</i>	1	280.00	<i>20</i>	280.00
REAR NUMBER PLATE <i>new</i>	1	25.00	<i>+</i>	25.00
REAR NUMBER PLATE FRAME <i>new</i>	1	50.00	<i>+</i>	50.00
REAR RH FENDER GLASS SEALANT <i>new</i>	1	80.00	<i>+</i>	80.00
REAR TAILGATE '70KM' STICKER <i>new</i>	1	25.00	<i>15</i>	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>+</i>	50.00
REAR TAILGATE WINDSCREEN SEAL <i>new</i>	1	80.00	<i>60</i>	80.00
Subtotal before discount				670.00
Percentage discount 0%				0.00
Sub-total 2				670.00
Parts-total				13,007.80

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	<i>✓</i>	80.00
To remove, reinstall tailgate windscreen	<i>120</i>	150.00
To remove, reinstall fender glass	<i>+</i>	120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>40</i>	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	<i>900</i>	1,200.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	<i>80</i>	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<i>1100</i>	1,800.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

WOODLANDS 11 CAR RENTAL PTE LTD
 11 WOODLANDS CLOSE #03-17B WOODLANDS
 11
 SINGAPORE 737853

Contact : 86912787 85748408

TAX INVOICE

Repair Code : CLM18433
 Date in : 23/10/2024
 Vehicle Num. : GBK1145C
 Model : TOYOTA HIACE DX 2.8 AUTO
 Chassis/Eng# : GDH2012009574/1GD8495619

To apply anti-rust chemical on repaired and replaced panel.	2500	100	120.00
To remove, reinstall tailgate mechanism and check for function		80	80.00
	Labour Total		3,750.00
	Parts & Labour Total		16,757.80

*** This is a computer-generated document which requires no signature.***

page 4

Adrian L
 w/s 24/10/24

08 hrs

total 9608.50

w/s: 7.7K

7.71K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: