

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 25 Oct 2024

**Preliminary Advice**

Insured Vehicle No	: SJS9399Y	Accident Date	: 16/10/2024
TP Vehicle No	: SBS3164S	Assignment Date	: 24/10/2024
Make	: VOLVO B9TL	Est. Duration of Repair	: 1
Date of Inspection	: 24/10/2024		
Inspection At	: SBS TRANSIT PTE LTD (ULU PANDAN) (HQ) ULU PANDAN WS, 1 BUSINESS PARK DRIVE, SINGAPORE 608506. SINGAPORE 608506		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,003.25
Revised Amount	:S\$	3,003.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,003.25
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.