



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS GO - LEASE PTE LTD 1 TAMPINES NORTH DRIVE 1, #02-33, T SPACE SINGAPORE 528559		Ref: CS/TP24100433/Enh3e2 Date: 30/10/2024 Code: TP2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	-	<b>Veh. Inspected</b>	SGP 9061Y
<b>Policy No.</b>	-	<b>Coverage</b>	0
<b>Claim No.</b>	-	<b>Excess</b>	\$0.00
<b>Assign From</b>	-	<b>Assign Date</b>	25/10/2024
<b>2. Vehicle Details</b>			
<b>Make &amp; Model</b>	TOYOTA PRIUS C	<b>C.C</b>	1497
<b>Engine No.</b>	-	<b>Year of Reg.</b>	29/11/2016
<b>Chassis No.</b>	JTDKD3B3401588355	<b>Colour</b>	BLACK
<b>Odometer</b>	- KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>General</b>	FAIR
<b>Modification(s)</b>	RIMS: SPORTS RIM		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance (mm)</b>
<b>R/H Front Tyre</b>	195/60 R15	MICHELIN	5
<b>L/H Front Tyre</b>	195/60 R15	MICHELIN	5
<b>R/H Rear Tyre</b>	195/60 R15	MICHELIN	5
<b>L/H Rear Tyre</b>	195/60 R15	MICHELIN	5
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, N/S BODY AND INTERIOR. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	02/09/2024	<b>Inspection Date</b>	25/10/2024
<b>Survey held at</b>	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR: 15 Working Days			