

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2401172

INV Date : 28-10-2024

Reference CS3/SMR24100434/Eqp3e2

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SNK 2575X
Insured Veh. SMB 1422U
Claim No. BUS/10/24/5037
Policy No.
Accident Date 22/10/2024
Inspection Date 25/10/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		Ref:	CS3/SMR24100434/Eqp3e2	
		Date:	28/10/2024	
		Code:	SMR	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	SMB 1422U	Veh. Inspected	SNK 2575X	
Policy No.	-	Coverage	0	
Claim No.	BUS/10/24/5037	Excess	\$0.00	
Assign From	HUA YEN	Assign Date	24/10/2024	
2. Vehicle Details				
Make & Model	TOYOTA NOAH HYBRID	C.C	1797	
Engine No.	2ZR0B88837	Year of Reg.	23/07/2018	
Chassis No.	ZWR800329136	Colour	BLACK	
Odometer	186030 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	195/65 R15	YOKOHAMA	5	
L/H Front Tyre	195/65 R15	YOKOHAMA	5	
R/H Rear Tyre	195/65 R15	YOKOHAMA	5	
L/H Rear Tyre	195/65 R15	YOKOHAMA	5	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
5. General Information				
Accident Date	22/10/2024	Inspection Date	25/10/2024 (09:26)	
Survey held at	15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417808 - REPAIRER: 1ST AUTO PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K




PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K




PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K






PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K



PHOTOGRAPHS FOR VEHICLE NO. : SNK 2575K

