

Not Attached
21 Pgs @ 5050/-

AAD2410-071

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF553U

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHF553U

JTDKB3FUX03093820

200303878K

TOYOTA

PRIUS GEN 4

19/10/24

G.B.B.9682M/China.

25/2/2021

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, FLOOR UNDER, NO.1 LH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 SPOILER SUB-ASSY, REAR
- 1 SEAL, REAR SPOILER
- 1 GLASS, BACK WINDOW FIX
- 1 DAM, WINDOW GLASS ADHESIVE
- 1 LENS & BODY, REAR COMBINATION LAMP, LH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 LH
- 1 COVER, REAR COMBINATION LAMP, LH
- 1 LAMP ASSY, REAR, LH
- 1 LAMP ASSY, REAR, RH
- 1 WEATHERSTRIP, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 STAY ASSY, BACK DOOR, LH

LIST

\$	R	612.68	✓
\$	R	419.90	✓
\$	Sn	27.93	X
\$	CM	472.19	✓
\$	DIY	167.48	✓
\$	Sn	167.48	X
\$	CM	49.25	✓
\$	Sn	49.25	X
\$	Sn	220.50	X
\$	Sn	304.92	X
\$	Sn	290.43	X
\$	Sn	159.39	X
\$	R	824.46	X
\$	R	1,099.46	X
\$	Sn	176.09	X
\$	R	1,443.86	X
\$	Sn R	1,986.92	X
\$	Sn	21.32	X
\$	Shattow	957.39	✓
\$	Sn	65.21	✓
\$	Br	428.19	✓
\$	Br	329.49	✓
\$	Br	88.41	✓
\$	Br	370.44	✓
\$	Sn	370.44	X
\$	Sn	469.25	X
\$	CM	1,156.89	✓
\$	Sn	305.66	X

AAD2410-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF553U

- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

\$	305.66	X
\$	77.18	X
\$	77.18	X
\$	68.88	—
\$	68.88	—
\$	90.30	—
TOTAL \$	13,722.96	
25% \$	3,430.74	
\$	10,292.22	

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP

\$	700.00	X
\$	95.00	601N
\$	150.00	401N
\$	200.00	X
\$	130.00	301N
\$	80.00	301N
\$	80.00	301N
\$	180.00	301N
\$	250.00	X
\$	85.00	X
\$	65.00	X

TOTAL \$	2,015.00
-----------------	-----------------

TOTAL PARTS \$	12,307.22
-----------------------	------------------

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$	300.00	801
----	--------	-----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	380.00	X
----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	1,600.00	4001
----	----------	------

AAD2410-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF553U

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	8801
To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201

TOTAL \$ 5,030.00

Over All Total \$ 17,337.22

(PART-BY-PART) Repair Days

12 DAYS

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF553U

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SUPPLEMENTARY

PART

- 1 MOULDING SUB-ASSY, ROOF TOP
- 1 MOULDING, ROOF DRIP SIDE FINISH, CENTER LH

AAD2410-071

SHF553U

JTDKB3FUX03093820

200303878K

TOYOTA

PRIUS GEN 4

19/10/2024

GBB9682M/CHINA

24/5/2019

LIST

	\$	<i>myern</i> 829.50	—
	\$	<i>thru</i> 80.12	—
TOTAL	\$	909.62	
25%	\$	227.40	
	\$	682.21	