

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	06:04 HRS
ACCIDENT DATE	23-Jun-24
BUS CAPTAIN NAME	PHOON POON ONN
THIRD PARTY CLAIM AGAINST	China Taiping Insurance

BUS REGISTRATION NUMBER	SMB1532K
BUS TYPE (SD/DD)	SD
BUS ROUTE NO.	
BUS ADVERT (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	OS REAR TAIL LAMP COVER	1	\$ 924.00
2	OS REAR REFLECTOR RH	1	\$ 92.40
		9% GST	\$ 91.48
		PARTS TOTAL COST	\$ 1,107.88

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- • DISMANTLE AND REPLACE ITEM NO: 1-2	\$ 1,300.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :- • RADIATOR DOOR • RADIATOR DOOR BOTTOM PANEL • OS REAR SUPPORT PILLAR	\$ 1,950.00
SPRAY PAINTING :- • RADIATOR DOOR • RADIATOR DOOR BOTTOM PANEL • OS REAR TAIL LAMP COVER	\$ 1,920.00
SPRAY PAINTING \$640 PER PANEL LABOUR CHARGES \$650 PER DAY	\$ 465.30
	LABOUR TOTAL COST \$ 5,635.30

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Hand signed and subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

BUS TYPE (SD / DD)	SD
Signature:	LOSS OF USE COST
Date:	

DATE IN	23/Jun/2024
DATE & TIME SURVEY	
DATE OUT	
TOTAL NUMBER OF DAYS	5
	\$1,500.00

SUMMARY

SECTION NO.	COST
1	\$ 1,107.88
2	\$ 5,635.30
3	\$ 1,500.00
TOTAL	\$ 8,243.18

Tanfer 97495749

wp 25/6/24 & 31st Jun

p/p resurvey before paint 4 days
tanfer c/luhantocur

914.76

2580

\$3494.76

4 days