


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 21.10.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **PC7522J**
MODEL : **TOYOTA HIACE**
DATE OF ACCIDENT : 18.10.2024
TIME OF ACCIDENT : 13:45 HOURS

Xiao Tong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delud</i>	1	\$ 479.00	\$ 479.00
2	REAR BUMPER SIDE RETAINER <i>3 pc</i>	2	\$ 55.00	\$ 110.00
3	REAR BUMPER BRACKET <i>2 pc</i>	4	\$ 21.20	\$ 84.80
4	TAIL LAMP RH <i>Crack'd</i>	1	\$ 390.00	\$ 390.00
5	TAILLAMP LOWER GARNISH RH <i>ton</i>	1	\$ 167.00	\$ 167.00
6	TAILLAMP LOWER GARNISH RETAINER RH <i>new</i>	1	\$ 65.00	\$ 65.00
7	TAILGATE <i>dent'd</i>	1	\$ 2,054.30	\$ 2,054.30
8	TAILGATE LOGO <i>new</i>	1	\$ 75.20	\$ 75.20
9	TAILGATE CENTER MOULDING (CHROME) <i>new</i>	1	\$ 674.80	\$ 674.80
10	TAILGATE EMBLEM "HIACE" <i>3 pc</i>	1	\$ 57.40	\$ 57.40
11	TAILGATE EMBLEM "GL"	1	\$ 58.40	\$ 58.40
12	TAILGATE STOPPER <i>new</i>	1	\$ 28.00	\$ 28.00
13	TAILGATE WEATHERSTRIP <i>ton</i>	1	\$ 395.00	\$ 395.00
14	TAILGATE WEATHERSTRIP PROTECTOR <i>Delud</i>	1	\$ 485.20	\$ 485.20
15	TAILGATE INNER LOCK <i>new</i>	1	\$ 475.60	\$ 475.60 385
16	TAILGATE LOWER LOCK <i>new</i>	1	\$ 45.20	\$ 45.20
17	TAILGATE LOWER CORNER GARNISH <i>new</i>	2	\$ 19.60	\$ 39.20
18	REAR END PANEL (OUTER) <i>dent'd</i>	1	\$ 597.00	\$ 597.00
19	REAR END PANEL (EXTEND) RH <i>Repair</i>	1	\$ 362.10	\$ 362.10
20	REAR FLOOR PANEL <i>new</i>	1	\$ 1,888.90	\$ 1,888.90
21	REAR FLOOR PANEL MAT <i>new</i>	1	\$ 1,591.50	\$ 1,591.50

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC7522J**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 18.10.2024
 TIME OF ACCIDENT : 13:45 HOURS

22	REAR SIDE PANEL INNER TRIM RH <i>beuhd</i>	1	\$ 257.40	\$ 257.40
----	--	---	-----------	-----------

5400.90
4050.67

TOTAL PRICE \$ 10,381.00
 LESS 25% \$ 2,595.25
SUB TOTAL PRICE \$ 7,785.75

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
2	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
3	TAILLAMP LOWER GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00 <i>+</i>
4	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
5	TAILGATE CENTER MOULDING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
6	TAILGATE LOWER CORNER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
7	TAILGATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
8	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00 <i>40</i>
9	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00 <i>70</i>
10	TAILGATE STICKER '70KM/H' <i>new</i>	1	\$ 30.00	\$ 30.00 <i>15</i>
11	TAILGATE STICKER 'EMERGENCY EXIT' <i>new</i>	1	\$ 60.00	\$ 60.00 <i>-</i>
12	REAR END PANEL (OUTER) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
13	REAR END PANEL (EXTEND) SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
14	REAR FLOOR TOP BOARD <i>new</i>	1	\$ 1,800.00	\$ 1,800.00 <i>+</i>
15	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 350.00	\$ 350.00 <i>+</i>

305

TOTAL \$ 3,190.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING AND REPLACE PARTS	\$ 2,200.00	<i>700</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>600</i>
3	WIRNING, BULB CHECKING	\$ 180.00	<i>30</i>
4	TRANSFER TAILGATE MECHAISM	\$ 80.00	<i>60</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **PC7522J**
 MODEL : **TOYOTA HIACE**
 DATE OF ACCIDENT : 18.10.2024
 TIME OF ACCIDENT : 13:45 HOURS

5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	+
7	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	50
8	REMOVE AND REFIX REAR REVERSE CAMERA	\$ 80.00	50
9	REMOVE AND REFIX LINING & SEATS	\$ 480.00	+
10	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 100.00	+
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	+

1610

TOTAL \$ 5,220.00

Adnan L
 F/S 22/10/24
 06 hrs

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,975.75
 TOTAL LABOUR COST : \$ 5,220.00
 TOTAL REPAIR COST : \$ 16,195.75

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Acknowledged by Repairer
 Signature

total: 5965.67
 L/S: 4750 ✓