

ASS. REC. BY:

REF:

CS/MSL 24100440/Kap3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/ MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

13/11

212mp @ 3000k Cash

(Red \$4076.60, 45%)

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 25/11 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / +B+ (\$

MER-TP

5000

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Not withaird
 11 Sep @ 500ch
 Resurvey After Party
 4 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SKJ 8887Y

S/N Parts Description

Unit Price Amt

1 Rear tailgate	Bz	\$1,690.00	\$1,690	✓
2 Rear tailgate emlem	me	\$128.00	\$128.00	✓
3 Rear tailgate reflector LH	cm	\$339.20	\$339.20	✓
4 Rear tailgate lock	R	\$343.00	\$343.00	X
5 Rear tailgate rubber	lu	\$195.80	\$195.80	X
6 Rear bumper	Bu	\$1,288.30	\$1,288.30	✓
7 Rear bumper reinforcement	Bz	\$632.30	\$632.30	✓
8 Rear bumper inner bracket LH	cm	\$132	\$132	✓
9 Rear bumper reflector LH	cm	\$90.00	\$90.00	✓
10 Taillamp LH	wt	\$598.00	\$598.00	✓
11 Rear end panel	R	\$1,135.00	\$1,135.00	X

Special Nett

1 Rear bumper clips	me	\$50.00	\$50.00	✓
2 Rear No. plate	lu	\$60.00	\$60.00	X
3 Rear windscreen sealant	me	\$80.00	\$80.00	40sm
4 Rear bumper reverse sensor	wt/1h01	\$285.00	\$285.00	✓

Labour

1 To remove and refit damaged parts, cut/weld damaged areas.	\$800.00	500l
2 To spray paint on affected areas.	\$800.00	550l
3 To remove and refit rear windscreen	\$200.00	120l
4 To remove and refit reverse sensor	\$100.00	50l
5 Check wiring	\$50.00	20l
6 Tuff coating	\$80.00	30l

\$2,030.00

Page 1

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: