

Not withaird  
 11 Sep @ 500ch  
 Resurvey After Party  
 4 days

# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SKJ 8887Y

## S/N Parts Description

Unit Price Amt

1 Rear tailgate	R	\$1,690.00	\$1,690	✓
2 Rear tailgate emlem	me	\$128.00	\$128.00	✓
3 Rear tailgate reflector LH	cm	\$339.20	\$339.20	✓
4 Rear tailgate lock	R	\$343.00	\$343.00	X
5 Rear tailgate rubber	lu	\$195.80	\$195.80	X
6 Rear bumper	Bu	\$1,288.30	\$1,288.30	✓
7 Rear bumper reinforcement	R	\$632.30	\$632.30	✓
8 Rear bumper inner bracket LH	cm	\$132	\$132	✓
9 Rear bumper reflector LH	cm	\$90.00	\$90.00	✓
10 Taillamp LH	wt	\$598.00	\$598.00	✓
11 Rear end panel	R	\$1,135.00	\$1,135.00	X

## Special Nett

1 Rear bumper clips	me	\$50.00	\$50.00	✓
2 Rear No. plate	lu	\$60.00	\$60.00	X
3 Rear windscreen sealant	me	\$80.00	\$80.00	40sm
4 Rear bumper reverse sensor	wt/1hoy	\$285.00	\$285.00	✓

## Labour

1 To remove and refit damaged parts, cut/weld damaged areas.	\$800.00	500l
2 To spray paint on affected areas.	\$800.00	550l
3 To remove and refit rear windscreen	\$200.00	120l
4 To remove and refit reverse sensor	\$100.00	50l
5 Check wiring	\$50.00	20l
6 Tuff coating	\$80.00	30l

\$2,030.00

Page 1

**LKK Auto Consultants** hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: