



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/ 0D

TP LonPec
Veron.

LKK

DATE 12/11/2024 OUR REF: UAPL1719
REPAIR ESTIMATE YOUR TOYOTA HIACE NO GBG2228L

- 1 REAR TAILGATE ASSY *Deled*
- 4 REAR TAILGATE WINDSCREEN DAM KIT *new*
- 1 REAR TAILGATE TOYOTA EMBLEM *new*
- 1 REAR TOYOTA HIACE STICKER *new*
- 1 REAR TAILGATE OUTER GARNISH *new*
- 1 REAR TAILGATE LOCK *new*
- 1 REAR TAILGATE LOCK CONTROL *new*
- 1 REAR TAILGATE LOCK STRIKER *new*
- 1 REAR TAILGATE WEATHERSTRIP *new*
- 1 REAR BUMPER ASSY *Deled*
- 10 REAR BUMPER CLIP *new*
- 2 REAR BUMPER SIDE RETAINER *new*

4216.70
3162.52

\$	2,344.60	✓
\$	21.60	✓
\$	78.60	✓
\$	102.40	✓
\$	286.80	✓
\$	419.60	✓
\$	479.90	✓
\$	93.10	✓
\$	255.50	✓
\$	512.80	✓
\$	50.00	30
\$	64.80	✓
\$	4,703.70	
\$	1,175.93	
\$	3,527.78	

LESS 25%.....

SPECIAL NETT:-

- 1 REAR WINDSCREEN GLASS DAM RUBBER *new*
- 1 REAR TAILGATE 70KM/H STICKER *new*
- 1 REAR TAILGATE 6 PAX STICKER *new*
- 1 REAR SET REVERSE SENSER *new*
- 1 REAR NUMBER PLATE *new*

290

\$	60.00	✓
\$	15.00	✓
\$	15.00	✓
\$	280.00	✓
\$	50.00	✓

LABOUR CHANGE:-

- TO DISM/REWIRE DAMAGED PORTION
- TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS
- TO PUTTY AND RESPRAY DAMAGED PORTION
- TO SPARY UNDERCOATING IN REPAIR
- TO DISM/RENEW REAR WINDSCREEN GLASS

980

\$	120.00	30
\$	1,000.00	400
\$	1,000.00	400
\$	200.00	30
\$	140.00	120
\$	6,407.78	

Total: 4432.52

4/5: 3.5K ✓
04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: