



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 ATTN: ERIC WOO			Ref: CS/LPC24100442/Avh3e2(N) Date: 04/04/2025 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 4683Y	Veh. Inspected	GBG 2228L
	Policy No.		Coverage (\$)	0.00
	Claim No.	23/24/24/VC05/030081	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	24/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTFHT02P800212222	Colour	SILVER
	Odometer	102923 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	YOKOHAMA	6 mm
	L/H Front Tyre	195 R15C	YOKOHAMA	6 mm
	R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm
	L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/10/2024	Inspection Date	12/11/2024
	Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	