

**CLOVER AUTO PTE LTD**

1002 TOA PAYOH INDUSTRIAL PARK #03-1423

TOA PAYOH INDUSTRIAL PARK

SINGAPORE 319074

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 01/11/2023

Page: 1 of 2

Not Authorised
90086608
28/10/23
L/S # 121600/
Edapho Affix
7 days.

ATTN: MOTOR CLAIM DEPARTMENT

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SLS9265B**MODEL : HONDA VEZEL****POLICY NO :****CHASSIS NO : RU31213583****YEAR OF MANUFACTURE :****DATE / TIME OF ACCIDENT: 16/10/2023 Time: 1340Hrs at TENGAH AIRBASE****THIRD PARTY VEHICLE NO: MID34888**

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price		Amount
S/N			S\$		S\$
1	HEADLAMP LH		\$ 1,975.80	CNE	\$ 1,975.80 ✓
2	HEADLAMP RH		\$ 1,975.80	holder CNE	\$ 1,975.80 ✓
3	HEADLAMP LOWER LH <i>broader</i>		\$ 135.20	CNE	\$ 135.20 ✓
4	HEADLAMP SIDE BRACKET LH		\$ 58.80	CNE	\$ 58.80 ✓
5	FRONT WINDSCREEN	142850	\$ 2,133.56	CNE	\$ 2,133.56 ✓
6	FRONT WINDSCREEN MOULDING		\$ 39.00	HER	\$ 39.00 ✓
7	BONNET	1020.00	\$ 1,068.00	BNE	\$ 1,068.00 ✓
8	BONNET HINGE RH		\$ 64.80	BNE	\$ 64.80 ✓
9	BONNET HINGE LH		\$ 64.80	BNE	\$ 64.80 ✓
10	BONNET SIDE RUBBER SEAL LH		\$ 64.90	TOR	\$ 64.90 ✓
11	BONNET CENTRE SEAL		\$ 64.90	TR	\$ 64.90 ✓
12	BONNET DAMPER RH		\$ 54.90	NZ	\$ 54.90 X
13	BONNET DAMPER LH		\$ 54.90	NZ	\$ 54.90 X
14	FRONT FENDER LH		\$ 480.70	DD/BNE	\$ 480.70 ✓
15	FRONT FENDER INNER SHEILD		\$ 139.20	TOR	\$ 139.20 ✓
16	FRONT FENDER INNER GANISH LH		\$ 95.20	11	\$ 95.20 X
17	FRONT BUMPER		\$ 594.90	D.S	\$ 594.90 ✓
18	FRONT BUMPER RETAINER LH		\$ 62.10	CNE	\$ 62.10 ✓
19	TOW COVER FRONT		\$ 25.00	11	\$ 25.00 X
20	FOG LAMP LH		\$ 256.90	CNE	\$ 256.90 ✓
21	FOG LAMP COVER		\$ 173.00	TOR	\$ 173.00 ✓
22	FOG LAMP BRACKET LH		\$ 142.90	CNE	\$ 142.90 ✓
23	FRONT BUMPER LOWER SPOILER		\$ 358.00	TOR	\$ 358.00 ✓
24	FRONT BUMPER LOWER GRILLE		\$ 174.50	11	\$ 174.50 X
25	FRONT BUMPER LOWER LIP SEAL		\$ 228.10	11	\$ 228.10 X
26	FRONT REINFORCEMENT BAR		\$ 345.00	BNE	\$ 345.00 ✓
27	FRONT REINFORMENET BAR PROTECTOR LH		\$ 63.70	NZ	\$ 63.70 X
28	FRONT GRILLE		\$ 289.90	CNE	\$ 289.90 ✓

97551

29	FRONT GRILLE BASE	318.00	\$ 582.10	CN	\$ 582.10	✓
30	HONDA EMBLEM FRONT	38.50	\$ 152.00	111	\$ 152.00	✓
31	FRONT SUPPORT PANEL	576.20	\$ 958.20	301	\$ 958.20	✓
32	TOP SUPPORT GANISH <i>ganish</i>	211.80	\$ 324.00	701	\$ 324.00	✓
33	FRONT WHEEL HOUSING LH		\$ 684.20	R	\$ 684.20	X
34	FRONT SUPPORT PANEL TOP GANISH		\$ 192.00	Repair	\$ 192.00	X
35	FRONT SUPPORT PANEL SIDE GANISH LH		\$ 136.20	711	\$ 136.20	✓
36	AIR DUCT <i>cleaner box</i>		\$ 392.50	701	\$ 392.50	✓
37	CONDENSOR	880.00	\$ 1,320.00	Buy/put	\$ 1,320.00	✓
38	AIRCON PIPING		\$ 472.00	11	\$ 472.00	X
39	AIRCON FAN BLADE		\$ 174.20	301	\$ 174.20	✓
40	AIRCON FAN CROWLING <i>Cowling</i>		\$ 168.80	CNA	\$ 168.80	✓
41	RADIATOR		\$ 1,296.60	CN	\$ 1,296.60	✓
42	RADIATOR CROWLING <i>Cowling</i>		\$ 168.80	CNA	\$ 168.80	✓
43	RADIATOR FAN BLADE		\$ 117.20	301	\$ 117.20	✓
44	RADIATOR FAN MOTOR		\$ 388.20	701	\$ 388.20	✓
45	FAN CROWLING		\$ 88.50	Repair	\$ 88.50	X
46	FUSE BOX		\$ 1,247.36	CNA	\$ 1,247.36	X
47	FUSEBOX COVER		\$ 192.90	11	\$ 192.90	X
48	WIRE HARNESS		\$ 117.90	11	\$ 117.90	X
49	FRONT UNDERCARRIAGE COVER		\$ 450.00	11	\$ 450.00	X
50	HEADLIGHT LEVEL SENSOR		\$ 292.30	11	\$ 292.30	X
51	FRONT WHEEL ARCH LH		\$ 250.00	711	\$ 250.00	✓
52	EXHAUST MANIFOLD		\$ 492.10	CNA	\$ 492.10	✓
53	ENGINE MOUNTING		\$ 498.20	11	\$ 498.20	X

Sub-Total: 22,338.72
Less: 20% discount - 4,467.74
Total Parts after 20% discount: 17,870.98

Special Nett Items

1	ANTI-RUST COATING	4	80.00		320.00	60
2	Front Fender Clips	45/1set	100.00	11	100.00	X
3	FRONT BUMPER CLIPS	45/1set	100.00	11	100.00	30
4	TOP GANISH CLIPS	1 set	100.00	11	100.00	30
5	FRONT WINSCREEN SEALANT	1	100.00	11	100.00	40
6	FRONT WINDSCREEN SEAL	1	100.00	11	100.00	20

Total Parts: 820.00

Labour Charges For Front

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.		2,000.00	1000
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities		2,000.00	1100
3	Provide skill labour to disconnect and check electrical wiring		150.00	50
4	Dismantle and transfer door fitting and mechanism to new door to facilitate repair	11	150.00	X
7	Reset Engine Management system with diagnostic fault		400.00	60
8	Provide skill labour to remove and check undercarriage	11	350.00	X
9	Provide labour to for wheel alignment	11	150.00	X
10	Provide skill labour to remove and replace front winscreen		200.00	120

Total Labour:

5,400.00

P-1659176
202
13273.41
180
2330
15783.41

Total Parts & Labour:	<u>24,090.98</u>
Grand Total:	<u><u>24,090.98</u></u>

Estimate Repair Duration	<u>10 days</u>
--------------------------	----------------

ACCIDENT VEHICLE OF : SLS9265B

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR:

Survey attended by:

Name : _____
Company : _____
Date : _____
Time : _____
Contact No : _____
Email : _____

